

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE			Ref:	CS3/ASM21002321/T1vf3e2	
	8 SHENTON WAY TOWERSINGAPO	-		Date:	01/04/2021	
	ATTN : YU DOMIN	IC YISHAN	(Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 3265Y	Veh. Inspected		GBK 3538P	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M0359N	Excess (\$)		0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date		18/02/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTFHT02PX00250387	Colour		WHITE	
	Odometer	35959 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/60 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	195/60 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	195/60 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	195/60 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FR				
5.	General Information					
	Accident Date	10/02/2021	Inspect Date / Ti	ime	10/03/2021 (04:00 PM)	
	Survey held at QAS AUTO PTE LTD					
	3018A UBI ROAD 1 #01-23 SINGAPORE 408711					
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21002321/T1vf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser