


ASS. REC. BY: *Perl.*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s *Camfort Layang*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *2* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SHC 8768E* Yr Regn: *19 Nov 2015*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /
 Truck / Trailer or
 Make: *Hyundai* 140 1.7 c.c 1685
 Colour: *Blue* A/C: Insured / Std / NI / NA
 Sp Reading: *534391* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *KMHLB41UM 64080587*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Ni / S/Rim / STD A/Rim or
 Tyre Size: F: *205/60R16*
 R: *11*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *westlake*

Front Rear
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. _____ D.O.I. *18-02-21*

Survey held at *W/S*
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *4:15pm*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>No Body injured.</i>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

_____ \$ + RS. _____ \$

Photos

Other

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Visual Insp (\$

SHOT ON MI A2
 MI DUAL CAMERA