

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002327/AGS3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKW7194B	Insured Vehicle No :	SMV6151M
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	6370051911SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW7194B		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B3530822
Reg. Date:	12/11/2015 (Man. Year: 2015)	Chassis No:	GK81000669
Colour:	White	Odometer:	53395 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,827.50	10,096.40	8,731.10	46.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,910.00	3,410.00	2,500.00	42.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,737.50	13,506.40	11,231.10	45.40
Approved Total (Overridden) (S\$)		10,800.00		

Nett Amount (S\$)	24,737.50	10,800.00	13,937.50	56.34
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,902.00		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 15/02/2021

Estimated Period of Repair: 10.0 days

Inspected At: Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6, #01-43
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,193.40 F	*1,193.40 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	110.20 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	331.80 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	37.40 F	*37.40 FL
5	1		*REAR BOOT LID SHUTTLE LOGO	Necessary	55.00 F	*55.00 FL
6	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	97.20 F	*- FL
8	1		*REAR BOOT LID CAMERA	Damaged	680.00 FS	*380.00 FS
9	1		*REAR BOOT LID CENTER CHROME MOULDING	Cracked	383.10 F	*383.10 FL
10	2		*REAR BOOT LID SIDE REFLECTOR	Cracked	681.60 F	*681.60 FL
11	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	76.70 F	*76.70 FL
12	2		*REAR BOOT LID WINDSCREEN SIDE MOULDING	Not Necessary	303.60 F	*- FL
13	1		*REAR BOOT LID INNER LOCK	Jammed	158.90 F	*158.90 FL
14	1		*+REAR BOOT LID INNER RUBBER	Cut	108.60 F	*108.60 FL
15	1		*+REAR BOOT LID INNER TRIM BOARD	Cracked	320.20 F	*320.20 FL
16	2		*REAR TAIL LAMP	Cracked	1,141.00 F	*1,141.00 FL
17	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
18	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	421.60 F	*- FL
19	1		*REAR BUMPER	Distorted	1,209.60 F	*1,150.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	53.00 F	*53.00 FL
21	10		*REAR BUMPER CLIP	Necessary	39.00 F	*39.00 FL
22	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
23	1		*REAR BUMPER TOWING COVER	Distorted	25.00 F	*25.00 FL
24	2		*REAR BUMPER SIDE REFLECTOR	Cracked	90.00 F	*90.00 FL
25	2		*REAR BUMPER SIDE REFLECTOR COVER	Cracked	90.60 F	*90.60 FL
26	1		*REAR END PANEL	Distorted	631.50 F	*631.50 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	155.50 F	*155.50 FL
28	1		*REAR END PANEL LOCK SWITCH	Not Necessary	159.20 F	*- FL
29	2		*REAR FENDER	Repair	2,421.80 F	*- FL
30	2		*REAR FENDER INNER TRIM BOARD	Cracked	911.20 F	*911.20 FL
31	16		*REAR FENDER INNER TRIM BOARD CLIP	Necessary	104.00 F	*60.00 FL
32	1		*REAR SPARE TYRE PANEL	Buckled	1,056.20 F	*1,056.20 FL
33	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	655.00 F	*585.00 FL
34	1		*REAR SPARE TYRE PANEL INNER TOP COVER	Not Necessary	608.00 F	*- FL
35	1		*REAR SPARE TYRE PANEL RUBBER COVER	Not Necessary	286.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SPARE TYRE PANEL STORAGE BOX	Deformed	322.00 F	*322.00 FL
37	1		*REAR SPARE TYRE PANEL FOAM STORAGE BOX	Cracked	265.00 F	*265.00 FL
38	1		*REAR SPARE TYRE PANEL SPANNER BOX	Not Necessary	295.40 F	*- FL
39	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
40	1		*REAR EXHAUST	Bent	788.60 F	*788.60 FL
41	1		*REAR CENTER EXHAUST	Bent	988.00 F	*988.00 FL
42	2		*REAR EXHAUST MOUNTING	Not Necessary	56.00 F	*- FL
43	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	107.60 F	*- FL
44	2		*REAR BUMPER FOAM	Cracked	130.00 F	*130.00 FL
45	1		*REAR TAIL LAMP PANEL	Dented	315.00 F	*315.00 FL
46	1		*REAR SPARE TYRE PANEL STORAGE BOX COVER	Cracked	52.00 F	*52.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,827.50	12,475.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,379.10
Total Parts (\$\$)	18,827.50	10,096.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	280.00	180.00
2	TO RMEOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	160.00
4	TO REMOVE & REFIT REAR CAMERA	New	180.00	50.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	GUM	New	50.00	50.00
7	TO CHECK WIRING	New	100.00	30.00
8	TOWING FEE	New	150.00	0.00
9	TUFF KOTE	New	150.00	120.00
10	PANEL BEATING	New	2,400.00	1,400.00
11	SPRAY PAINTING	New	2,000.00	1,250.00
Gross Labour Cost (S\$)			5,910.00	3,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >