

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002329/UGA3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993855
Claimant Vehicle No :	SMT8152H	Insured Vehicle No :	GBA9550R
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	1001925435SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT8152H		
Make & Model:	BMW 535I, 3.0 (A)	Engine No:	05417472N55B30A
Reg. Date:	06/10/2010 (Man. Year: 2010)	Chassis No:	WBAFR72040C579673
Colour:	Black	Odometer:	125431 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/35Z R20	Rear Tyre Size:	285/30Z R20
Front Left Side:	Tourador 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,331.70	4,388.48	8,943.22	67.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	620.00	2,680.00	81.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,631.70	5,008.48	11,623.22	69.89
Approved Total (Overridden) (S\$)		4,000.00		

Nett Amount (S\$)	16,631.70	4,000.00	12,631.70	75.95
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos Spring, #08-1339
Singapore 470130

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	2,680.15 FL	*1,357.90 FL
2	1		*FRONT BUMPER CENTRE LOWER GARNISH	Not Necessary	268.92 FL	*- FL
3	1		*FRONT BUMPER LOWER SIDE GRILLE RH	Not Necessary	286.11 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Scratched	275.10 FL	*275.10 FL
5	1		*FRONT BUMPER CENTRE MOUNT	Not Necessary	286.32 FL	*- FL
6	1		*FRONT BUMPER RH TOP MOUNT	Not Necessary	254.65 FL	*- FL
7	1		*FRONT BUMPER RH LOWER MOUNT	Not Necessary	241.55 FL	*- FL
8	1		*SET FRONT BUMPER SENSOR RING	Not Necessary	45.72 FL	*- FL
9	4		*FRONT BUMPER ANGLE SENSOR	Shorted (1 PCS ONLY)	1,144.00 FL	*215.00 FL
10	1		*FRONT BUMPER RIVET	Necessary	21.00 FL	*21.00 FL
11	1		*FRONT BUMPER BODY NUT	Not Necessary	9.00 FL	*- FL
12	1		*FRONT BUMPER REPAIR KIT	Not Necessary	112.20 FL	*- FL
13	1		*FRONT BUMPER LOGO	Necessary	145.82 FL	*68.00 FL
14	1		*FRONT BUMPER CENTRE GRILLE GARNISH	Not Necessary	714.64 FL	*- FL
15	1		*FRONT FENDER RH	Repair	1,568.32 FL	*- FL
16	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	213.30 FL	*- FL
17	1		*FRONT FENDER INNER SHIELD EXPANDING RIVETS	Not Necessary	19.80 FL	*- FL
18	1		*FRONT HEADLAMP NOZZLE GARNISH RH	Not Necessary	198.41 FL	*- FL
19	1		*FRONT HEADLAMP NOZZLE RH	Not Necessary	296.42 FL	*- FL
20	1		*FRONT HEADLAMP RH	Scratched	2,682.45 FL	*2,682.45 FL
21	1		*FRONT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*FRONT RIM RH	Not Necessary	1,832.65 FL	*- FL
23	1		*FRONT NUMBER PLATE W/GARNISH	Not Necessary	80.00 FS	*- FS
24	1		*FRONT TYRE RH	Not Necessary	620.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,996.53	4,619.45
- List Item Discount on L Items 5.00/5.00% (\$\$)	664.83	230.97
Total Parts (\$\$)	13,331.70	4,388.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,200.00	200.00
2	TO PUTTY ,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL FRONT DOOR COMPONENTS	New	150.00	0.00
5	TO CONDUCT ALL WHEEL ALIGNMENT	New	150.00	0.00
6	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	450.00	0.00
7	TO RUST PROOF AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (S\$)			3,300.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >