



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 6100X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LEFT SLIDING DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,951.80	-
1	LEFT SLIDING DOOR OUTER GARNISH RAIL (CONSISTENT)	NOT NECESSARY	227.50	-
1	LEFT SLIDING DOOR RAIL (CONSISTENT)	NOT NECESSARY	193.80	-
1	LEFT SLIDING DOOR GLASS MOULDING (CONSISTENT)	NOT NECESSARY	245.10	-
1	LEFT SLIDING DOOR LOWER HINGE LINKAGE (CONSISTENT)	NOT NECESSARY	227.50	-
1	LEFT SLIDING DOOR WEATHER STRIP (CONSISTENT)	NOT NECESSARY	320.40	-
1	LEFT SLIDING DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	386.10	-
1	REAR SIDE PANEL N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,673.80	-
1	REAR SIDE PANEL AIR -DUCT N/S (CONSISTENT)	NOT NECESSARY	98.20	-
1	REAR TAILLAMP N/S (CONSISTENT)	NOT NECESSARY	794.80	-
1	REAR TAILLAMP PANEL N/S (CONSISTENT)	NOT NECESSARY	297.20	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	786.40	-
1	REAR BUMPER BRACKET N/S (CONSISTENT)	NOT NECESSARY	186.20	-
	LESS 25% DISCOUNT		-1,847.20	-
			5,541.60	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR SIDE PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR TAILLAMP PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR STEEL RIM N/S (SN) (CONSISTENT)	NOT NECESSARY	520.00	-
1	REAR TYRE N/S (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
			960.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS .INCLUSIVE OF THE REPAIR OF LEFT SLIDING DOOR ,REAR SIDE PANEL N/S AND REAR BUMPER .		1,400.00	500.00
	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS .		1,600.00	600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & INSTALL LEFT SLIDING DOOR GLASS .	NOT NECESSARY	150.00	-
	TO REMOVE & INSTALL LEFT SLIDING DOOR COMPONENTS.	NOT NECESSARY	150.00	-
	TO REMOVE & INSTALL INTERIOR SIDE PANEL TRIM ,ROOF TRIM TO FACILITATE REPAIRS .	NOT NECESSARY	200.00	-
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING .	NOT NECESSARY	50.00	-
	TO CONDUCT ALL WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO RUST PROOF AFFECTED AREAS .	NOT NECESSARY	200.00	-
			4,080.00	1,100.00
<b>GRAND TOTAL</b>			<b>10,581.60</b>	<b>1,100.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,100.00</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/ASM21002334/Ubs3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.