

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21002339/QPS3Q2
Date: 17/08/2021

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | |
| Claimant Vehicle No : | SHC4576T | Insured Vehicle No : | SKX7096X |
| Date of Loss: | 14/02/2021 | Nature of Claim: | TP |
| | | Claim No: | 9989998938SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SHC4576T | | |
| Make & Model: | TOYOTA PRIUS HYBRID, 1.8 CVT (A) | Engine No: | 2ZR6230436 |
| Reg. Date: | 10/12/2014 (Man. Year: 2014) | Chassis No: | JTDKN36U305753773 |
| Colour: | Maroon | Odometer: | 438034 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Sailun 6 mm | Rear Left Side: | Sailun 6 mm |
| Front Right Side: | Sailun 6 mm | Rear Right Side: | Sailun 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 10,155.65 | 1,350.23 | 8,805.42 | 86.70 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,836.00 | 680.00 | 2,156.00 | 76.02 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,991.65 | 2,030.23 | 10,961.42 | 84.37 |
| Approved Total (Overridden) (S\$) | | 1,750.00 | | |

| | | | | |
|--|------------------|-----------------|------------------|--------------|
| Nett Amount (S\$) | 12,991.65 | 1,750.00 | 11,241.65 | 86.53 |
| <hr/> | | | | |
| + Car Rental (2.0 x S\$133.75/day) (S\$) | | 267.50 | | |
| + Doc/Search Fee (S\$) | | 7.00 | | |
| + Other Costs (S\$) | | 180.00 | | |
| | | <hr/> | | |
| Nett Liability (S\$) | | 2,204.50 | | |
| | | <hr/> | | |
| Global Sum Settlement (S\$) | | 2,100.00 | | |
| | | <hr/> | | |

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------|------------|-----------|
| 1 | 1 | | *NAME PLATE (HYBRID) (DISC 25%) | Necessary | 51.90 F | *38.93 F |
| 2 | 1 | | *HEAD LAMP RH (DISC 10%) | Scratched | 945.20 F | *850.68 F |
| 3 | 1 | | *LENS & BODY ,FR TURN RH (DISC 10%) | Cracked | 511.80 F | *460.62 F |
| 4 | 1 | | *BUMPER CLIPS | Serviceable | 1.61 F | *- F |
| 5 | 1 | | *BUMPER SUPPORT F/RH | Serviceable | 76.40 F | *- F |
| 6 | 1 | | *BUMPER SUPPORT F/LH | Serviceable | 76.40 F | *- F |
| 7 | 1 | | *BUMPER ENERGY ABSORBER FRT | Serviceable | 78.80 F | *- F |
| 8 | 1 | | *BUMPER REINFORCEMENT FRT | Serviceable | 498.40 F | *- F |
| 9 | 1 | | *ARM SUB-ASSY ,FR BUMPER LH | Serviceable | 250.40 F | *- F |
| 10 | 1 | | *ARM SUB-ASSY ,FR BUMPER RH | Serviceable | 250.40 F | *- F |
| 11 | 1 | | *BUMPER GRILLE SUB-ASSY ,LOWER | Serviceable | 311.10 F | *- F |
| 12 | 1 | | *WIRE ,ENGINE ROOM ,NO.3 | Serviceable | 242.00 F | *- F |
| 13 | 1 | | *GRILLE ,RADIATOR | Serviceable | 310.60 F | *- F |
| 14 | 1 | | *GRILLE ,RADIATOR LOWER NO.2 | Serviceable | 94.60 F | *- F |
| 15 | 1 | | *BUMPER LIP FRT | Serviceable | 139.60 F | *- F |
| 16 | 1 | | *BUMPER FRT ABSORBER LOWER | Serviceable | 127.70 F | *- F |
| 17 | 1 | | *UNDER COVER CENTER | Serviceable | 448.30 F | *- F |
| 18 | 1 | | *FENDER LINDER FRT/RH | Serviceable | 171.70 F | *- F |
| 19 | 1 | | *FENDER LINER PAD ,FR WHEEL RH | Serviceable | 49.30 F | *- F |
| 20 | 1 | | *WHEEL ,DISC FRONT | Serviceable | 1,484.20 F | *- F |
| 21 | 1 | | *TYRE | Serviceable | 126.74 F | *- F |
| 22 | 1 | | *MOULDING BODY ,RH | Serviceable | 673.60 F | *- F |
| 23 | 1 | | *WHEEL HUB FRT | Serviceable | 549.70 F | *- F |
| 24 | 1 | | *MIRROR ASSY RH | Serviceable | 1,307.10 F | *- F |
| 25 | 1 | | *MIRROR LAMP RH | Serviceable | 65.30 F | *- F |
| 26 | 1 | | *COVER ,OUTER MIRROR, RH | Serviceable | 107.40 F | *- F |
| 27 | 1 | | *FENDER FRT/RH | Repair | 723.40 F | *- F |
| 28 | 1 | | *BUMPER FRT | Repair | 482.00 F | *- F |

F=Franchise part.

Total Parts (S\$)
10,155.65
1,350.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING & BODY WORK | New | 676.00 | 200.00 |
| 2 | SPRAY PAINT | New | 1,476.00 | 400.00 |
| 3 | TO DO WHEEL ALIGNMENT /TYRE BALANCING | New | 120.00 | 0.00 |
| 4 | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | New | 120.00 | 0.00 |
| 5 | TO RMEOVE AND REFIX WING MIRROR | New | 120.00 | 0.00 |
| 6 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| 7 | TO CHECK WIRING AND SYSTEM FUNCTION | New | 80.00 | 20.00 |
| 8 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| 9 | TOWING CHARGE | New | 84.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 2,836.00 | 680.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >