

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21002341/QGS3Q2
Date: 16/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070121796	
Claimant Vehicle No :	SMB1333T	Insured Vehicle No :	SGW8833G	
Date of Loss:	09/02/2021	Nature of Claim:	TP	Claim No: 0575575447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1333T		
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Engine No:	50340971954086
Reg. Date:	25/03/2013 (Man. Year: 2012)	Chassis No:	WMAA22ZZ4D7001776
Colour:	Multi-colour	Odometer:	827086 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,218.90	416.99	6,801.91	94.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,886.00	2,186.00	700.00	24.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,104.90	2,602.99	7,501.91	74.24
Approved Total (Overridden) (S\$)		2,500.00		

Nett Amount (S\$)	10,104.90	2,500.00	7,604.90	75.26
+ Loss of Use (6.0 x S\$250.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,007.00		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 4.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ,INDICATOR SIDE LED (MAN BUS)	Cracked	186.10 F	*186.10 FL
2	2		*LOCK ,LEVER:LATCH WITH KEY FOR MAN A22	Crumpled	55.00 F	*55.00 FL
3	1		*STICKER SMRT	Necessary	200.00 FS	*200.00 FS
4	1		*PANEL,SIDE:R6,FOR MAN A22 BUS	Repair	1,776.80 F	*- FL
5	1		*PANEL,SIDE:R7,FOR MAN A22 BUS	Repair	885.50 F	*- FL
6	1		*PANEL ,SIDE:R8,FOR MAN A22 BUS	Repair	330.70 F	*- FL
7	1		*PANE,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	Repair	710.70 F	*- FL
8	1		*PANE,SIDE:R10 ,FOR MAN A22 BUS	Repair	192.70 F	*- FL
9	1		*PANEL ,SIDE:R11,FOR MAN A22 BUS	Repair	1,782.50 F	*- FL
10	1		*COVER :REAR TAIL LAMP ,RH ,FOR MAN A22 BUS	Repair	974.70 F	*- FL
11	1		*WHEEL ARCH TRIM	Repair	124.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,218.90	441.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	24.11
Total Parts (\$)	7,218.90	416.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,296.00	1,126.00
Gross Labour Cost (S\$)			2,886.00	2,186.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >