

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002342/APS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900102489
Claimant Vehicle No :	SKB566T	Insured Vehicle No :	SML6243J
Date of Loss:	12/02/2021	Nature of Claim:	TP
		Claim No:	8609218321SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB566T	Engine No:	BFS074651
Make & Model:	VOLKSWAGEN NEW BETTLE, 1.6 (A)	Chassis No:	WVWZZZ9CZ9M558290
Reg. Date:	04/06/2009 (Man. Year: 2009)	Odometer:	98887 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.55	4,835.07	1,041.48	17.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,810.00	530.00	22.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,216.55	6,645.07	1,571.48	19.13
Approved Total (Overridden) (S\$)		5,300.00		

	(S\$)	8,216.55	5,300.00	2,916.55	35.50
+ GST 7.00/7.00% (S\$)		575.16	371.00	204.16	35.50
Nett Amount (S\$)		8,791.71	5,671.00	3,120.71	35.50
+ Car Rental (4.0 x S\$100.00/day) (S\$)			400.00		
+ Doc/Search Fee (S\$)			2.00		
Nett Liability (S\$)			6,073.00		

INSPECTION

Date of Assignment: 15/02/2021

Date Inspected: 15/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Dented	1,999.30 FL	*1,695.00 FL
2	1		*FRT DOOR OUTER MOULDING RH	Not Necessary	167.70 FL	*- FL
3	1		*FRT DOOR GLASS CHANNEL RH	Not Necessary	188.90 FL	*- FL
4	1		*FRT DOOR GLASS REGULATOR ASSY RH	Damaged	510.70 FL	*510.70 FL
5	1		*FRT DOOR FRAME BLACK GARNISH RH	Necessary	99.70 FL	*99.70 FL
6	1		*FRT DOOR TRIM RH	Cracked	900.70 FL	*825.00 FL
7	1		*RH SIDE ROCKER PANEL	Dented	1,800.60 FL	*1,380.00 FL
8	1		*FRT FENDER RH	Deformed	861.90 FL	*861.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,529.50	5,372.30
- List Item Discount on L Items 10.00/10.00% (S\$)	652.95	537.23
Total Parts (S\$)	5,876.55	4,835.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	1,000.00	900.00
2	TO SPRAY PAINTING	New	1,000.00	750.00
3	TO SPRAY UNDERSEAL	New	80.00	80.00
4	TO REMOVE AND REFIT CUSHION	New	80.00	0.00
5	TO REMOVE AND REPLACE RH DOOR TRIM	New	80.00	40.00
6	TO REMOVE AND REFIT RH DOOR GLASS	New	100.00	40.00
			Gross Labour Cost (S\$)	2,340.00
				1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >