

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21002345/GVF3E2**Date:** 28/06/2021**REFERENCE**

Insured/Claimant: KENNETH LIM CHER KIONG Policy No: MPC21A00004800
Date of Loss: 11/02/2021 Nature of Claim: OD Claim No: DMPC2100058H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFK9850A**
Make & Model: AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A) Engine No: CAXA01529
Reg. Date: 31/12/2011 (Man. Year: 2011) Chassis No: WAUZZZ8P3CA075340
Colour: Black Odometer: 117959 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$25,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,919.58	7,227.36	11,692.22	61.80
Miscellaneous Items	190.00	40.00	150.00	78.95
Labour	1,730.00	750.00	980.00	56.65
Paintwork Labour	1,080.00	400.00	680.00	62.96
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,919.58	8,417.36	13,502.22	61.60
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	21,919.58	5,000.00	16,919.58	77.19
+ GST 7.00/7.00% (S\$)	1,534.37	350.00	1,184.37	77.19
Nett Amount (S\$)	23,453.95	5,350.00	18,103.95	77.19

INSPECTION

Date of Assignment: 18/02/2021 Present Location: Automobile Integrated Management Pte Ltd (HQ)
Automobile Integrated Management Pte Ltd (HQ)
Date Inspected: 19/02/2021 Inspected At: 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Singapore 415933
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2021)

Parts: 143 AUDI A3 1.4 SEDAN TFSI COD S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFK9850A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air cleaner inlet duct	Not Necessary	196.55 FL	*- FL
2	1		Air-cond condenser	Bent	965.00 FL	*765.00 FL
3	1		Air-cond discharge hose	Not Necessary	481.50 FL	*- FL
4	1		Air-cond suction hose	Not Necessary	411.50 FL	*- FL
5	1		Bonnet	Buckled	1,689.90 FL	*1,689.90 FL
6	1		Bonnet insulator	Not Necessary	241.45 FL	*- FL
7	10		Bonnet insulator clips	Not Necessary	55.00 FL	*- FL
8	1		Bonnet lock	Not Necessary	180.95 FL	*- FL
9	1		Bumper fog lamp cover LH	Not Necessary	110.20 FL	*- FL
10	1		Bumper fog lamp cover RH	Not Necessary	110.20 FL	*- FL
11	1		Bumper fog lamp LH, front	Not Necessary	281.50 FL	*- FL
12	1		Bumper fog lamp RH, front	Not Necessary	281.50 FL	*- FL
13	1		Bumper lower cover,front	Missing	28.85 FL	*28.85 FL
14	1		Bumper reinforcement, front	Bent	715.00 FL	*611.00 FL
15	1		Bumper, front	Deformed	1,558.50 FL	*1,236.00 FL
16	1		Fender LH, front	Not Necessary	816.50 FL	*- FL
17	1		Fender RH, front	Not Necessary	816.50 FL	*- FL
18	1		Headlamp LH	Not Necessary	2,455.00 FL	*- FL
19	1		Headlamp RH	Broken	2,455.00 FL	*1,859.00 FL
20	2		Horn	Not Necessary	179.90 FL	*- FL
21	1		Radiator	Not Necessary	860.50 FL	*- FL
22	1		Radiator fan	Not Necessary	1,150.00 FL	*- FL
23	1		Radiator lower hose	Not Necessary	121.60 FL	*- FL
24	1		Radiator upper hose	Not Necessary	110.65 FL	*- FL
25	1		*Bonnet safety lock FRONT	Not Necessary	115.60 FL	*- FL
26	1		*Bonnet damper	Not Necessary	191.55 FL	*- FL
27	1		*Bumper sponge	Cracked	142.65 FL	*118.00 FL
28	1		*Bumper side grid LH	Not Necessary	68.85 FL	*- FL
29	1		*Bumper side grid RH	Not Necessary	68.85 FL	*- FL
30	1		*Front Grille Assy	Cracked	1,260.00 FL	*650.00 FL
31	1		*Front Support panel	Bent	895.00 FL	*650.00 FL
32	1		*Air intercooler	Not Necessary	899.60 FL	*- FL
33	1		*Checking of front electrical wiring		-	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	19,915.35	7,607.75
- List Item Discount on L Items 5.00/5.00% (\$\$)	995.77	380.39
Total Parts (\$\$)	18,919.58	7,227.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Air Con oil (NOT NECESSARY)	65.00	0.00
2	1	Number plate, front (BENT)	60.00	40.00
3	1	Radiator coolant (NOT NECESSARY)	65.00	0.00
Sub Total (\$\$)			190.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Respray painting	New	1,080.00	400.00
Labour Items				
2	Checking of front electrical wiring	New	50.00	30.00
3	Towing charge	New	100.00	0.00
4	Diagnose, erase fault memory after repair	New	350.00	0.00
5	Remove, refix A/C condenser and refill A/C Gas	New	180.00	120.00
6	Panel beating, cut, weld remove and replace all parts	New	1,050.00	600.00
Gross Labour Cost (\$\$)			2,810.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >