



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 8188G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER ASSY	TO REPAIR SEE LABOUR	2,585.00	-
1	SET FRONT BUMPER LEFT LH SIDE BRACKET	NOT NECESSARY	485.00	-
1	FRONT BUMPER LH SENSOR	NOT NECESSARY	580.00	-
1	FRONT FENDER PROTECTOR N/S	CUT	205.00	160.00
1	FRONT LEFT DOOR COVER	TO REPAIR SEE LABOUR	2,500.00	-
1	REAR LEFT DOOR	TO REPAIR SEE LABOUR	2,500.00	-
1	FRONT LEFT SUSPENSION ASSY	NOT NECESSARY	1,850.00	-
1	FRONT LEFT LOWER CONTROL ARM	NOT NECESSARY	695.00	-
1	FRONT LEFT KNUCKLE ARM	NOT NECESSARY	885.00	-
1	FRONT LEFT WHEEL HUB WITH BEARING	NOT NECESSARY	655.00	-
	LESS 10% DISCOUNT		-1,294.00	-16.00
			11,646.00	144.00
<b><u>SPECIAL NETT ITEMS</u></b>				
10	BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
6	BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
6	FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT RIM (SN)	CUT	1,200.00	900.00
1	REAR RIM (SN)	CUT	1,200.00	900.00
1	ALUMINUM SIDE STEP (SN)	CUT	1,000.00	800.00
1	SIDE STEP SUPPORT PANEL (SN)	NOT NECESSARY	800.00	-
			4,340.00	2,600.00
<b><u>LABOUR</u></b>				
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY,FRONT LEFT DOOR COVER AND REAR LEFT DOOR.		1,500.00	600.00
	TO PUTTY AND SPRAY PAINTING FRONT PORTION.		2,000.00	1,100.00
	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA.	NOT NECESSARY	200.00	-

Report Ref No. CS/SMO21002357/Uvf3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE,ARM,SUSPENSION AND KNUCKLE AND BEARING ETC.	NOT NECESSARY	350.00	-
	TO BALANCE THE FRONT AND BEHIND WHEEL.	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	COMPUTER RESET THE WHOLE SYSTEM.	NOT NECESSARY	150.00	-
			4,480.00	1,760.00
<b>GRAND TOTAL</b>			<b>20,466.00</b>	<b>4,504.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/SMO21002357/Uvf3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.