



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002357/Uvf3q2 Date: 05/03/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 2617S	Veh. Inspected	SGS 8188G	
Policy No.	D20MTPV01005554	Coverage (\$)	0.00	
Claim No.	CMTD2100528/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	19/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X6 (A)	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAFG22020L597064	Colour	BLACK	
Odometer	159204 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50 R19	MICHELIN	6 mm	
L/H Front Tyre	255/50 R19	MICHELIN	6 mm	
R/H Rear Tyre	285/45 R19	MICHELIN	6 mm	
L/H Rear Tyre	285/45 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2021	Inspection Date	22/02/2021	
Survey held at	BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @ KAKI BUKIT			
Repairer	XIN YUN AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	