

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III21002358/AVF3Q2
Date: 22/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0006540_01
Claimant Vehicle No :	SJV7948K	Insured Vehicle No :	SMJ383M
Date of Loss:	18/02/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0000770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV7948K	Engine No:	3ZZ4957715
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106163066
Reg. Date:	09/02/2010 (Man. Year: 2009)	Odometer:	229183 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,997.57	2,817.95	1,179.62	29.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,860.00	1,140.00	38.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,997.57	4,677.95	2,319.62	33.15
Approved Total (Overridden) (\$\$)		3,700.00		
Nett Amount (\$\$)	6,997.57	3,700.00	3,297.57	47.12

INSPECTION

Date of Assignment:	19/02/2021	
Date Inspected:	19/02/2021 Inspected At:	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV7948K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	495.00 FL	*495.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	72.00 FL	*72.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	145.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Cracked	129.50 FL	*129.50 FL
5	1		*REAR BUMPER REINFORCEMENT ROD	Not Necessary	117.50 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET	N/s Dented	196.20 FL	*98.10 FL
7	1		*REAR END PANEL	Dented	581.40 FL	*581.40 FL
8	1		*REAR END PANEL TOP GARNISH	Cracked	192.50 FL	*192.50 FL
9	1		*BOOTLID	Buckled	695.60 FL	*695.60 FL
10	1		*BOOTLID LOCK	Not Necessary	189.20 FL	*- FL
11	1		*BOOTLID WEATHERSTRIPE	Cut	195.50 FL	*195.50 FL
12	2		*BOOTLID REFLECTOR	Not Necessary	520.40 FL	*- FL
13	2		*TAILLAMP	O/s Cut/N/s Cracked	650.00 FL	*650.00 FL
14	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	289.30 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
17	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
18	1		*SET REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
19	2		*BOOTLID REFLECTOR SPONGE GASKET	Not Necessary	40.00 FS	*- FS
20	2		*TAILLAMP SPONGE GASKET	Necessary	40.00 FS	*40.00 FS
21	1		*TOYOTA LOGO	Necessary	42.00 FL	*42.00 FL
22	1		*1.6 EMBLEM	Necessary	45.00 FL	*45.00 FL
23	1		*COROLLA EMBLEM	Necessary	46.00 FL	*46.00 FL
24	1		*ALTIS EMBLEM	Necessary	48.00 FL	*48.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,160.10	3,640.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,162.53	822.65
Total Parts (\$\$)	3,997.57	2,817.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	WIRING CHECK	New	50.00	30.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE AND REFIT UPHOLSTERY	New	150.00	60.00
6	TUFF COAT	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
Gross Labour Cost (\$\$)			3,000.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >