

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21002361/Qqf3e2	
	8 SHENTON WAY AXA TOWERSING			Date:	01/04/2021	
	ATTN : TAN WAN	CONG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 142D	Veh. Inspected	l	SMM 3285C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03330	Excess (\$)		0.00	
	Assign From	TAN WAN CONG	Assign Date		19/02/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF3416MK5047097	Colour		WHITE	
	Odometer	161801 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	CONTINENTAL		6 mm	
	L/H Front Tyre	225/45 R17	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/45 R17	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/45 R17	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	IICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	15/02/2021	Inspect Date /	Time	23/02/2021 (12:31 PM)	
	Survey held at	5035 ANG MO KIO IND. PARK 2	#01-349			
	Repairer	ZOLAR AUTO SERVICES				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21002361/Qqf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser