

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21002363/R1VD3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	LUO JUNYANG	Policy No:	2070051262		
Date of Loss:	19/02/2021	Nature of Claim:	OD	Claim No:	8631416780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS9269D		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH755439
Reg. Date:	23/03/2020 (Man. Year: 2019)	Chassis No:	KNAF3416ML5069456
Colour:	Red	Odometer:	16061 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,182.00	5,832.80	2,349.20	28.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,486.00	5,730.00	1,756.00	23.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,668.00	11,562.80	4,105.20	26.20
+ GST 7.00/7.00% (S\$)	1,096.76	809.40	287.36	26.20
Nett Amount (S\$)	16,764.76	12,372.20	4,392.56	26.20

INSPECTION

Date of Assignment:	19/02/2021		
Date Inspected:	19/02/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Deformed	651.00 F	*651.00 FL
2	1		*COVER-RR BUMPER LWR	Cracked	241.00 F	*241.00 FL
3	1		*COVER-RR BUMPER FOG LAMP,RH	Cracked	19.00 F	*19.00 FL
4	1		*COVER-RR BUMPER FOG LAMP,LH	Cracked	19.00 F	*19.00 FL
5	1		*LAMP ASSY-SIDE T-SIGNAL,RH	Cracked	181.00 F	*181.00 FL
6	1		*LAMP ASSY-SIDE T-SIGNAL,LH	Serviceable	181.00 F	*- FL
7	1		*EXTN WIRING ASSY-BWS	Serviceable	207.00 F	*- FL
8	1		*BRACKET-RR BEAM UPR MTG,RH	Serviceable	9.00 F	*- FL
9	1		*BRACKET-RR BEAM UPR MTG,LH	Serviceable	9.00 F	*- FL
10	1		*BEAM-RR BUMPER	Cracked	318.00 F	*318.00 FL
11	1		*BRACKET-RR BEAM LWR,CTR	Serviceable	6.00 F	*- FL
12	2		*BRACKET-RR BEAM LWR MTG	Serviceable	12.00 F	*- FL
13	1		*ANTENNA ASSY-SMARTKEY	Serviceable	46.00 F	*- FL
14	1		*STAY-RR BUMPER RH	Serviceable	65.00 F	*- FL
15	1		*STAY-RR BUMPER LH	Serviceable	65.00 F	*- FL
16	1		*BRACKET-ASSY RR BPR SIDE UPR,R	Cracked	31.00 F	*31.00 FL
17	1		*BRACKET-ASSY RR BPR SIDE UPR,L	Cracked	25.00 F	*25.00 FL
18	1		*PANEL ASSY-TRUNK LID	Bent	1,297.00 F	*1,297.00 FL
19	1		*HINGE ASSY-TRUNK LID,LH	Serviceable	97.00 F	*- FL
20	1		*HINGE ASSY-TRUNK LID,RH	Serviceable	97.00 F	*- FL
21	1		*PANEL ASSY-BACK	Bent	324.00 F	*324.00 FL
22	1		*EMBLEM-CERATO	Necessary	28.00 F	*28.00 FL
23	1		*LOGO ASSY-KIA SUB	Necessary	32.00 F	*32.00 FL
24	1		*TRIM ASSY-TRUNK LID	Deformed	202.00 F	*202.00 FL
25	1		*W/STRIP-TRUNK LID OPNG	Necessary	100.00 F	*100.00 FL
26	1		*LATCH ASSY-TRUNK LID	Serviceable	112.00 F	*- FL
27	1		*PANEL ASSY-RR COMB LAMP HSG,RH	Bent	135.00 F	*135.00 FL
28	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Cut	675.00 F	*675.00 FL
29	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Broken	675.00 F	*675.00 FL
30	1		*LAMP ASSY-REAR COMB INSIDE,RH	Cut	608.00 F	*608.00 FL
31	1		*LAMP ASSY-REAR COMB INSIDE,LH	Cracked	608.00 F	*608.00 FL
32	1		*LAMP ASSY-CENTER GARNISH	Cracked	690.00 F	*690.00 FL
33	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
34	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
35	1		*PANEL ASSY-RR COMB LAMP HSG,LH (Supplementary)	Bent	139.00 F	*139.00 FL
36	1		*STAY-RR BUMPER LH (Supplementary)	Bent	65.00 F	*65.00 FL
37	1		*STAY-RR BUMPER RH (Supplementary)	Bent	65.00 F	*65.00 FL
38	10		*CLIPS (Supplementary)	Necessary	20.00 F	*20.00 FL
39	1		*TRIM ASSY-RR TRANSVERSE (Supplementary)	Broken	41.00 F	*41.00 FL
40	1		*FILM-ANTI CHIPPG RH (Supplementary)	Necessary	27.00 F	*27.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,182.00	7,276.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,443.20
Total Parts (\$\$)	8,182.00	5,832.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WASH,WAX,CLEAN,VACUUM & PARTIAL ZERTON	New	46.00	0.00
2	RENEW REAR BUMPER,BOOTLID,REAR END PANEL,REAR LAMP HOUSING RH.REPAIR REAR FENDER RH & LH,REAR COMPARTMENT	New	2,000.00	2,000.00
3	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	120.00
5	SPRAY PAINT FOR REAR BUMPER,BOOTLID,REAR END PANEL,REAR COMPARTMENT,REAR FENDER RH & LH,REAR LAMP HOUSING RH	New	3,360.00	1,750.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
9	REPLACE LH & RH REAR COMB LAMP HOUSING,REPAIR REAR FLOOR PANEL (Supplementary)	New	800.00	800.00
10	RESPRAY ON LH & RH REAR COMB LAMP HOUSING,AND REAR FLOOR PANEL (Supplementary)	New	480.00	480.00
11	SUPPLY ONE SET OF PARKING SENSOR (Supplementary)	New	220.00	220.00
12	SUPPLY & REPLACE REAR LICENSE PLATE WITH FRAME (Supplementary)	New	50.00	50.00
Gross Labour Cost (\$\$)			7,486.00	5,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >