

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM21002367/Qqf3e2	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date	9: 16/03/2021	
	ATTN: TAN JUN H	ONG	Cod	e: ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 6115M	Veh. Inspected	FBA 5087M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M032FR	Excess (\$)	0.00	
	Assign From	TAN JUN HONG	Assign Date	19/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA T135	c.c	135	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	5YP202762	Colour	WHITE	
	Odometer	728842 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90-17	MICHELIN	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90-17	MICHELIN	5 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.			D	
5.	5. General Information				
	Accident Date	07/02/2021	Inspect Date / Time	19/02/2021 (04:49 PM)	
	Survey held at	SPEEDY MOTOR CYCLE SERV	ICE CENTRE		
	BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21002367/Qqf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser