

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI21002368/R1VF3E2

**Date:** 03/03/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19352619000  
**Claimant Vehicle No :** YJ8828C **Insured Vehicle No :** YN768Z  
Date of Loss: 02/07/2020 Nature of Claim: TP Claim No: SNM20D202338C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YJ8828C**  
Make & Model: HINO XZU710R, 4.0 D HKMQK3-UBS (M) Engine No: N04CUS26974  
Reg. Date: 20/04/2016 (Man. Year: 2016) Chassis No: JHHUCS3H20K016725  
Colour: Multi-colour Odometer: 305031 km  
Engine Capacity: 4009 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 7.00 R15 Rear Tyre Size: 7.00 R15 (D)  
Front Left Side: OHTSU 7 mm Rear Left Side: OHTSU 7/7 mm  
Front Right Side: OHTSU 7 mm Rear Right Side: OHTSU 7/7 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 19/02/2021  
Date Inspected: 22/02/2021 Inspected At: Yee Keong Motor Engineering (HQ)  
Estimated Period of Repair: 9.0 days No. 14 Penjuru Road  
Singapore 609125

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

# REPAIR DETAILS

|               |  |   |
|---------------|--|---|
| Reference     |  |   |
| Part Source:  | (Last Synchronised: 03 Mar 2021)   |   |
| Parts:        | N/A  | HINO XZU710R 4.0 D HKMQK3-UBS (M) (Model not available in database) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                                   |
| Print Code:   | (Unsubmitted, no print-code for YJ8828C)   |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >