

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002374/GTF3E2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070017266
Claimant Vehicle No : SLN9112K **Insured Vehicle No :** GBJ2950T
Date of Loss: 14/02/2021 Nature of Claim: TP Claim No: 1096826741SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN9112K**
Make & Model: TOYOTA WISH, 1.8 X CVT (A) Engine No: 2ZR1961062
Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: JTDGG20W40J007084
Colour: White Odometer: 0 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/02/2021
Date Inspected: 19/02/2021 Inspected At: A-Tec Automotive Pte Ltd (HQ)
8 Kaki Bukit Avenue 4 # 05-27 Premier
Singapore 415875
Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Missing	0.00 F	*- F
3	1		*FRT BUMPER	Broken	0.00 F	*- F
4	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Missing	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Missing	0.00 F	*- F
9	1		*FRT LH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
10	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
11	1		*FRT LH BUMPER FOG LAMP	Missing	0.00 F	*- F
12	1		*FRT RH BUMPER FOG LAMP	Missing	0.00 F	*- F
13	1		*FRT GRILLE	Missing	0.00 F	*- F
14	1		*FRT GRILLE EMBLEM	Missing	0.00 F	*- F
15	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
16	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Cracked	0.00 F	*- F
17	2		*HORN	Dented	0.00 F	*- F
18	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
19	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
20	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
21	1		*BONNET	Buckled	0.00 F	*- F
22	1		*BONNET EMBLEM	Bent	0.00 F	*- F
23	1		*BONNET LOCK	Bent	0.00 F	*- F
24	1		*BONNET INSULATOR	Bent	0.00 F	*- F
25	2		*BONNET HINGE	Bent	0.00 F	*- F
26	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
27	1		*AIR CON FAN ASSY	Cracked	0.00 F	*- F
28	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	Dented	0.00 F	*- F
29	1		*AIR CON SUCTION HOSE	Bent	0.00 F	*- F
30	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Dented	0.00 F	*- F
31	1		*AIR CON LIQUID PIPE	Bent	0.00 F	*- F
32	1		*RADIATOR	Dented	0.00 F	*- F
33	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
34	1		*RADIATOR FAN ASSY	Cut	0.00 F	*- F
35	1		*RADIATOR HOSE TOP	Bent	0.00 F	*- F
36	1		*RADIATOR EXPANSION TANK	Dented	0.00 F	*- F
37	1		*AIR DUCT	Cracked	0.00 F	*- F
38	1		*AIR CLEANER ASSY	Cracked	0.00 F	*- F
39	1		*FRT INLET MANIFOLD	Cracked	0.00 F	*- F
40	1		*FUSE BOX	Distorted	0.00 F	*- F
41	1		*WIPER WASHER TANK	Dented	0.00 F	*- F
42	1		*WIPER WASHER TANK MOTOR	Cracked	0.00 F	*- F
43	1		*ALTERNATOR ASSY	Cracked	0.00 F	*- F
44	1		*ABS PUMP CONTROL LINK	Cracked	0.00 F	*- F
45	1		*ENGINE TOP COVER	Bent	0.00 F	*- F
46	1		*ENGINE UNDER COVER	Bent	0.00 F	*- F
47	1		*ENGINE MOUNTING	Distorted	0.00 F	*- F
48	1		*FRT LH FENDER	Buckled	0.00 F	*- F
49	1		*FRT LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
50	1		*FRT RH FENDER	Buckled	0.00 F	*- F
51	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
52	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F
53	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
54	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
55	1		*ERP BRACKET	Necessary	0.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*WIPER PANEL GARNISH	Cut	0.00 F	*- F
57	1		*DASHBOARD ASSY	Broken	0.00 F	*- F
58	1		*STEERING WHEEL AIRBAG	Burst	0.00 F	*- F
59	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	0.00 F	*- F
60	1		*DASHBOARD AIRBAG	Burst	0.00 F	*- F
61	1		*DASHBOARD AIRBAG SENSOR	Necessary	0.00 F	*- F
62	1		*FRT RH SEAT BELT ASSY	Jammed	0.00 F	*- F
63	1		*FRT LH SEAT BELT ASSY	Jammed	0.00 F	*- F
64	2		*AIR CON CONDENSER SIDE AIR DEFLECTOR	Torn	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >