

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002375/T1GS3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100510543
Claimant Vehicle No :	SHB8054L	Insured Vehicle No :	SJX6588L
Date of Loss:	15/02/2021	Nature of Claim:	TP
		Claim No:	4364545371SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8054L	Engine No:	D4FDFH314445
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658264
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	369191 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,685.30	656.40	2,028.90	75.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	430.00	1,590.00	78.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,705.30	1,086.40	3,618.90	76.91
Approved Total (Overridden) (S\$)		850.00		

(S\$)	4,705.30	850.00	3,855.30	81.94
+ GST 7.00/7.00% (S\$)	329.37	59.50	269.87	81.94
Nett Amount (S\$)	5,034.67	909.50	4,125.17	81.94
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$62.76/day) (S\$)		188.28		
Nett Liability (S\$)		1,217.78		

INSPECTION

Date of Assignment: 19/02/2021

Date Inspected: 24/02/2021

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID EMBLEM	Not Necessary	27.00 FL	*- FL
2	1		*BOOTLID CRDI	Not Necessary	29.00 FL	*- FL
3	1		*BOOTLID LOWER GARNISH	Not Necessary	290.00 FL	*- FL
4	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
5	1		*REAR BUMPER LOWER COVER	Repair	206.00 FL	*- FL
6	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	*- FL
7	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
9	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	106.00 FL	*- FL
10	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
11	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR N/S & O/S	Not Necessary	92.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
14	1		*SET BOOTLID LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
15	1		*SET BOOTLID STICKERS	Not Necessary	100.00 FS	*- FS
16	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
17	1		*REAR BUMPER PROTECTOR	Not Necessary	80.00 FS	*- FS
18	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,915.00	726.00
- List Item Discount on L Items 10.00/10.00% (\$)	229.70	69.60
Total Parts (\$)	2,685.30	656.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/WELD ,CUT -OFF THE THE END PANEL,INCLUDING KNOCK -OUT ,STRAIGHTEM REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC	New	800.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL ,BOOTLID	New	800.00	200.00
5	TO APPLY RUSTPROOFIG ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (S\$)			2,020.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >