



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 5508M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (SN)	DEFORMED	2,016.00	2,016.00
1	FRONT BUMPER FIXING PARTS (SN)	NOT NECESSARY	187.00	-
1	FRONT BUMPER COVER LOWER CENTRE (SN)	NOT NECESSARY	156.00	-
4	FRONT BUMPER LOWER PULL STRAP (SN)	NOT NECESSARY	206.00	-
1	FRONT BUMPER GUIDE SECTION LH (SN)	NOT NECESSARY	63.00	-
1	FRONT BUMPER AIR GUIDE GRILLE (SN)	CRACKED	109.00	109.00
1	RADIATOR GRILLE (SN)	NOT NECESSARY	691.00	-
1	RADIATOR GRILLE COVER (SN)	NOT NECESSARY	98.00	-
1	FRONT BUMPER REINFORCEMENT (SN)	NOT NECESSARY	795.00	-
1	FRONT BUMPER IMPACT ABSORBER (SN)	NOT NECESSARY	83.00	-
1	FRONT SUPPORT PANEL TOP COVER (SN)	NOT NECESSARY	56.00	-
1	FRONT FENDER LH (SN)	DENTED	851.00	851.00
1	FRONT FENDER ATTACHMENT PARTS LH (SN)	NOT NECESSARY	72.00	-
1	FRONT FENDER TOP BRACKET LH-REAR (SN)	* CHECK	28.00	-
1	FRONT FENDER TOP BRACKET LH-FRONT (SN)	* CHECK	48.00	-
1	FRONT FENDER BRACE LH (SN)	* CHECK	96.00	-
1	FRONT FENDER LOWER BRACKET LH (SN)	* CHECK	62.00	-
1	FRONT WHEEL HOUSING LINER LH (SN)	NOT NECESSARY	169.00	-
1	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH (SN)	NOT NECESSARY	89.00	-
1	BONNET (SN)	DENTED	2,745.00	2,745.00
1	BONNET ATTACHMENT PARTS (SN)	NOT NECESSARY	165.00	-
1	BONNET EDGE PROTECTION SEAL-FRONT (SN)	NECESSARY	28.00	28.00
1	BONNET STRIKER (SN)	NOT NECESSARY	110.00	-
1	BONNET LOCK W/MICRO SWITCH (SN)	NOT NECESSARY	214.00	-
1	HEADLIGHT LH (SN)	CRACKED	2,641.00	2,641.00
1	HEADLIGHT WASHER LIFT CYLINDER LH (SN)	NOT NECESSARY	193.00	-
1	WING MIRROR MOUNTING LH (SN)	NOT NECESSARY	1,024.00	-
1	FRONT ALUMINIUM RIM LH (SN)	* CHECK	1,166.00	-
1	SUNDRIES (SN)	* CHECK	400.00	-

Report Ref No. CS/SGK21002386/Avf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NO PLATE (SN)	NOT NECESSARY	60.00	-
			14,621.00	8,390.00
	<b>LABOUR</b>			
	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		360.00	360.00
	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL/RENEW LHS WING MIRROR ASSY.		280.00	280.00
	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS HEADLIGHT.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		3,150.00	2,850.00
	TO RESPRAY FRONT BUMPER,BONNET,LHS FRONT FENDER,LHS FRONT DOOR,LHS WING MIRROR COVER,DOOR HANDLES,LHS REAR DOOR AND LHS REAR FENDER.		5,400.00	4,650.00
	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	NOT NECESSARY	280.00	-
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			9,942.00	8,612.00
<b>GRAND TOTAL</b>			<b>24,563.00</b>	<b>17,002.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,800.00 NETT)</b>				<b>17,002.00</b>

Report Ref No. CS/SGK21002386/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.