

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002390/ABA3Q2
Date: 10/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMW2598D	Insured Vehicle No :	SMK9319K
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	9578612084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW2598D	Engine No:	15E4E8AGL9250071
Make & Model:	M.G. TOURER, 1.5 (M)	Chassis No:	LSJA24U94LN035256
Reg. Date:	11/11/2020 (Man. Year: 2020)	Odometer:	4736 km
Colour:	Red		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,293.50	2,519.60	3,773.90	59.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	530.00	910.00	63.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,733.50	3,049.60	4,683.90	60.57
Approved Total (Overridden) (S\$)		2,400.00		

(S\$)	7,733.50	2,400.00	5,333.50	68.97
+ GST 7.00/7.00% (S\$)	541.35	168.00	373.35	68.97
Nett Amount (S\$)	8,274.85	2,568.00	5,706.85	68.97
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,998.00		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment: 19/02/2021

Date Inspected: 19/02/2021

Estimated Period of Repair: 2.0 days

Inspected At: SK Automobile Pte Ltd
8 Kaki Bukit Ave 4
#08-45/46 Premier @ Kaki Bukit
Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	750.00 FL	*750.00 FL
2	1		*REAR BUMPER LOWER GARNISH	Deformed	497.00 FL	*497.00 FL
3	1		*REAR BUMPER LOWER LID	Deformed	278.00 FL	*278.00 FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	33.00 FL	*- FL
5	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	96.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	688.00 FL	*688.00 FL
7	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Not Necessary	316.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	886.00 FL	*- FL
9	1		*TAILGATE LOCK	Not Necessary	197.00 FL	*- FL
10	1		*TAILGATE LOCK COVER	Not Necessary	18.00 FL	*- FL
11	1		*REAR EXHAUST	Not Necessary	2,070.00 FL	*- FL
12	4		*REAR EXHAUST MOUNTING	Not Necessary	124.00 FL	*- FL
13	4		*REAR PARKING SENSOR	Damaged (2 PCS ONLY)	540.00 FL	*270.00 FL
14	4		*REAR PARKING SENSOR BRACKET	Necessary (2 PCS ONLY)	122.00 FL	*61.00 FL
15	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*REAR BUMPER LOWER LID CLIPS	Necessary	50.00 FS	*20.00 FS
17	1		*REAR BUMPER ADHESIVE PROTECTOR GUARD	Necessary	240.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,955.00	2,774.00
- List Item Discount on L Items 10.00/10.00% (\$)	661.50	254.40
Total Parts (\$)	6,293.50	2,519.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO PANEL BEAT & STRAIGHTEN AFFECTED PANELS AND REPLACE ABOVE MENTIONED PARTS	New	560.00	250.00
2	TO SPRAY PAINT REAR BUMPER ,REVERSE PARKING SENSOR & REAR BUMPER UNDERTRAY	New	560.00	200.00
3	TO PERFORM REAR ELECTRICAL WIRING CHECKS AND FUNCTIONALITY CHECKS	New	160.00	30.00
4	INSTALLATION AND CALIBRATION /SETTING FOR REVERSE SENSOR	New	160.00	50.00
Gross Labour Cost (\$\$)			1,440.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >