



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 16.02.2021
Emailed : 27.03.2021, 12.30pm
Date Survey : 22.02.2021

VEHICLE NO : SMP 1799 J
MODEL : MIT OUTLANDER 2.0
WIP : 63067

Table with 2 columns: Description and Amount. Rows include Material (\$5,979.19), Labour (\$4,860.00), Sub-Total (\$10,839.19), Less Excess (\$600.00), Total (\$10,239.19), GST 7% (\$716.74), Grand Total (\$10,955.93), and Finalise By/Date (LOI / 27/03/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of [] Use / [] Rental

[] Claim Medical Fee / Others

[] Third Party Report -



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 09/03/2021	Cust No/Name	/CHIN SWEE KHONG
	Reg No/Reg Date	SMP1799J / 13/09/2019
	Date In/Mileage	09/03/2021/ 51513
	Chassis/Package	GF7W0602003 /#
	Engine No	4J11BJ0870
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	W01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	27/03/2021/ 12:14	BLD	260 / AiTing	63067

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH FRONT DOOR , LH REAR DOOR, LH REAR FENDER, REPAIR REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 2025.00
E PNT98000 RESPRAY ON LH FRONT DOOR, LH REAR DOOR, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1050.00
E PNT88000 REMOVE & REINSTALL LH FRONT DOOR COMPONENTS TO NEW PANEL				✓ 120.00
E PNT88000 REMOVE & REINSTALL LH REAR DOOR COMPONENTS TO NEW PANEL				✓ 120.00
E PNT88000 REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS, CARPETS & SEATS TO FACILITATE REPAIR				✓ 120.00
M SUNDRY REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALE, AND CONDUCT WHEEL BALANCING				✓ 30.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				✓ 120.00
E PNT88000 REMOVE & REINSTALL LH REAR FENDER QUARTER GLASS, AND CONDUCT WATER LEAK TEST				✓ 120.00
M SUNDRY SUPPLY QUARTER GLASS SEALANT				✓ 80.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				✓ 40.00
M SUNDRY				✓ 80.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.



PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 09/03/2021	Cust No/Name	/CHIN SWEE KHONG
	Reg No/Reg Date	SMP1799J / 13/09/2019
	Date In/Mileage	09/03/2021/ 51513
	Chassis/Package	GF7W0602003 /#
	Engine No	4J11BJ0870
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	W01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	27/03/2021/ 12:14	BLD	260 / AiTing	63067

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
APPLY BODY PANEL SEALANT ON AFFECTED AREAS				✓ 20.00
M SUNDRY				225.00
SUNDRIES				✓ 480.00
A 54900099 REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR → Supp.				-600.00
S SPECIALISTJOB SUPPLY LH REAR TIRE				
X EXC INSURANCE EXCESS				
X PANEL ASSY,FR DOOR,LH	977 1.00	✓ 982.00	23.00	756.14
X TAPE,FR DOOR SASH,LH	1.00	✓ 42.00	23.00	32.34
X PANEL ASSY,RR DOOR,LH	859 1.00	✓ 864.00	23.00	665.28
X HINGE,RR DOOR,LWR LH	1.00	✓ 43.00	23.00	33.11
X TAPE,RR DOOR SASH	1.00	✓ 42.00	23.00	32.34
X TAPE,RR DOOR SASH	1.00	✓ 42.00	23.00	32.34
X PANEL,QTR,OTR LH	1291 1.00	✓ 1298.00	23.00	999.46
X MOULDING,RR WHEEL ARCH,LH	1.00	✓ 160.00	23.00	123.20
X MOULDING,RR BUMPER,LH	1.00	✓ 106.00	23.00	81.62
X GLASS,QTR WINDOW,LH	1.00	? 713.00	23.00	549.01
X WHEEL,DISC LHR	1.00	✓ 974.00	23.00	749.98
X BODY KIT, OUTLANDER	1.00	✓ 1554.00	00.00	1554.00
X GARNISH,RR DOOR,LH	145 1.00	? 164.00	23.00	126.28
X GARNISH,FR DOOR,LH	168 1.00	? 190.00	23.00	146.30
X W/STRIP,RR DOOR OPNG,FR LH → Supp.	1.00	127.00	23.00	97.79
Z TEXT				
AIG OD CLAIM DOA : 16.02.21 SURVEYOR STEVE LKK 22.02.21 POLICY NO : 1900161688-01				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,979.19	Nett	10,239.19
Labour	4,130.00	7% GST on	716.74
Standard Menu	0.00		
Specialist Job	480.00	Total Payable	10,955.93
Diagnostics Job	0.00		
Sundry/Others	-350.00		
Total(w/o GST)	10,239.19		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMP 1799 J

<u>Materials</u>		<u>Cost (\$)</u>
1	W/Strip, RR door opng, Fr LH	127.00 ✓ TV
Total		127.00
Less 23%		29.21
Total Materials		97.79
<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & install fuel tank to facilitate repair	225.00 ✓
Total Labour		225.00
Taxable Amount		322.79
7% GST		22.60
Grand total		<u><u>345.39</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMP 1799J

WIP: 63067

(ADDITIONAL)

ch Sign Sto

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Grainish Front Door LH	? / SUPP		- CMT	
2	W/Strip Rear Door Open LWR QTR LH	? / SUPP		- TN	
3	Hinge Rear Door LWR LH	? / SUPP		- BT	Spec
4	Grainish Rear Rear Door LH	? / SUPP		- CMT	10/13/21
5	Glass QTR Window LH	? / SUPP		- nec	
6		? / SUPP			
7	to remove install fuel tank \$225	? / SUPP			Spec 15/3/19
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
15/3/21	Spec

MODEL: OUTLANDER 2.0

SURVEYOR: Steve @ LICK

Work Order: R001386
License: SMP 1799 J
Technician: 106 WENG SOON
Mileage: 51513
Date: 23.3.21 10:02

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
0°11'	0°12'	-0°10' 0°50'
2°11'	2°11'	2°05' 3°05'
0°02'	-0°01'	-0°02' 0°06'
11°52'	11°51'	11°15' 14°15'
12°03'	12°03'	11°05' 15°05'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°03'	0°04'	-0°10' 0°50'
3°00'	3°00'	2°05' 3°05'
0°02'	0°01'	-0°02' 0°06'
12°03'	12°02'	11°15' 14°15'
12°06'	12°06'	11°05' 15°05'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°08'	0°08'	-0°30' 0°30'
-0°49'	-0°49'	-0°30' 0°30'
-0°11'	-0°11'	
0°03'	0°00'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°36'	-0°34'	-1°15' 0°15'
0°06'	0°10'	0°02' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°54'	-0°58'	-1°15' 0°15'
0°09'	0°03'	0°02' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°19'	0°24'	-0°30' 0°30'
0°16'	0°13'	0°04' 0°24'
-0°01'	0°03'	

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20121-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2019MY

Reg no. SHP 17995
After very first-3x not set to Base all the fault
to Job Done
to Test drive check Condition.
to by D.C.

2021.03.22

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/AWSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		No DTCs	

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	