

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21002393/GPA3Q2**Date:** 07/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_01  
**Claimant Vehicle No :** SLJ1789G **Insured Vehicle No :** GBK5679C  
 Date of Loss: 18/02/2021 Nature of Claim: TP Claim No: MFL2021D0000851

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1789G**  
 Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CL8857  
 Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: JMYSRCY1AGU006151  
 Colour: White Odometer: 85743 km  
 Engine Capacity: 1590 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,819.98	656.00	1,163.98	63.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	590.00	880.00	59.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,289.98</b>	<b>1,246.00</b>	<b>2,043.98</b>	<b>62.13</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	3,289.98	1,000.00	2,289.98	69.60
<b>+ GST 7.00/7.00% (S\$)</b>	230.30	70.00	160.30	69.60
<b>Nett Amount (S\$)</b>	<b>3,520.28</b>	<b>1,070.00</b>	<b>2,450.28</b>	<b>69.60</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>1,226.45</b>		

INSPECTION

Date of Assignment: 19/02/2021  
 Date Inspected: 24/02/2021 Inspected At: Ryder Auto Pte Ltd (HQ)  
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit  
 Singapore 417921  
 Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 29 Dec 2022)**Parts:** 143      MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLJ1789G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	680.00 FL	*680.00 FL
2	1		*REAR N/S BUMPER REFLECTOR	Not Necessary	80.00 FL	*- FL
3	1		*REAR END PANEL	Not Necessary	581.60 FL	*- FL
4	1		*REAR ENFORCEMENT	Repair	320.60 FL	*- FL
5	8		*REAR BUMPER CLIPS	Necessary	24.00 FS	*24.00 FS
6	1		*REAR BUMPER TAPE	Necessary	20.00 FS	*20.00 FS
7	2		*REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,986.20</b>	<b>724.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	166.22	68.00
<b>Total Parts (\$)</b>	<b>1,819.98</b>	<b>656.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE DAMAGED PARTS	New	800.00	300.00
2	TO SPRAY PAINTING	New	500.00	250.00
3	TO CHECK WIRING	New	50.00	0.00
4	TO RE-SEAL ANTI-RUST	New	80.00	0.00
5	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	40.00	40.00
			<b>Gross Labour Cost (\$)</b>	<b>590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >