

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002396/TPA3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070117249
Claimant Vehicle No :	SLT2279C	Insured Vehicle No :	SMU3779C
Date of Loss:	17/02/2021	Nature of Claim:	TP
		Claim No:	6308831922SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT2279C	Engine No:	1NZR495128
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Chassis No:	NKE1657144310
Reg. Date:	23/10/2017 (Man. Year: 2017)	Odometer:	280393 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,923.22	1,203.00	2,720.22	69.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	630.00	970.00	60.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,523.22	1,833.00	3,690.22	66.81
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	5,523.22	1,450.00	4,073.22	73.75
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,657.45		
Global Sum Settlement (S\$)		1,650.00		

INSPECTION

Date of Assignment:	19/02/2021		
Date Inspected:	06/07/2021	Inspected At:	Tridente Automobili Pte Ltd (HQ) 30 Leng Kee Road #01-02 Singapore 159100
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Not Necessary	419.20 FL	*- FL
2	1		*RADIATOR GRILLE LOGO	Not Necessary	102.90 FL	*- FL
3	1		*HEAD LAMP LH	Cracked	1,204.50 FL	*825.00 FL
4	1		*HEAD LAMP RH	Not Necessary	1,204.50 FL	*- FL
5	1		*FRONT BUMPER	Deformed	929.60 FL	*681.00 FL
6	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	454.10 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	111.70 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	111.70 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	200.80 FL	*- FL
10	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	145.30 FL	*58.00 FL
11	1		*SET RADIATOR GRILEL CLIPS	Not Necessary	60.00 FS	*- FS
12	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
13	1		*SET FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	60.00 FS	*- FS
14	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,144.30	1,594.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,221.08	391.00
Total Parts (\$\$)	3,923.22	1,203.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER ,BOTH HEAD LAMP ,TO REPAIR FRONT FENDER LH ,FRONT SUPPORT PANEL ,AND REALIGN ON ALL ACCIDENT AFFECTED AREAS	New	800.00	200.00
2	TO PUTTY AND RESPRAY ON FRONT ACCIDENT PORTION	New	700.00	400.00
3	TO FOCUS HEAD LAMP AND CHECK WIRING	New	100.00	30.00
			Gross Labour Cost (\$\$)	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >