

LKK

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way, #09-16 AIG Building
Singapore 079120

Date : 18/02/2021
Vehicle : SLT2279C
Make/Model : Toyota Corolla Axio Hybrid 1.5
ORD : 2017
Chassis : NKE1657144310
ODO : 257744
ACC Date : 17/02/2021

Estimate

S/N	Qty	Description & Specification	Amount S\$
List Items			
1	1	Radiator grille	\$419.20 x un
2	1	Radiator grille logo	\$102.90 x un.
3	1	Head Lamp LH	\$1,204.50 ?
4	1	Head Lamp RH	\$1,204.50 x
5	1	Front bumper	\$929.60 de
6	1	Front bumper centre grille	\$454.10 x un
7	1	Front bumper side retainer LH	\$111.70 ng -
8	1	Front bumper side retainer RH	\$111.70 x un
9	1	Front bumper sponge	\$200.80 x un
10	1	Front fender "hybrid emblem" LH	\$145.30 na -
Total			\$4,884.30
Less 25%			\$1,221.08
S/Nett Total			\$3,663.23
S/Nett Items			
1	1set	Radiator grille clips	\$60.00 x un
2	1set	Front bumper clips	\$80.00 3over
3	1set	Front fender inner shield clips LH	\$60.00 x un
4	1pc	Front fender inner shield clips RH	\$60.00 x un
S/Nett Total			\$260.00
Labour			
1		To replace front bumper, both head lamp, to repair front fender LH, front support panel, and re-align on all accident affected areas	\$800.00 200.
2		To putty and respray on front accident portion	\$700.00 400
3		To focus head lamp and check wiring	\$100.00 30
Labour Total			\$1,600.00
Grand Total			\$5,523.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495749/62563571
WP' 6/7/21 @ 12:15pm
2/3 Resury after repair
Tanfer & lkkauto.com.
2-3 days