

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21002399/GPA3Q2

Date:

26/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : XB7439C**Insured Vehicle No :**

GBK4017U

Date of Loss: 13/02/2021

Nature of Claim:

TP

Claim No:

MFL2021D0000889

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XB7439C**

Make & Model: MITSUBISHI FV517JD2RDEB, 11.9 D (M)

Engine No: 6D24317162

Reg. Date: 27/12/2001 (Man. Year: 2001)

Chassis No: FV517JA00138

Colour: White

Odometer: 0 km

Engine Capacity: 11945 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11.00 R20

Rear Tyre Size: 11.00 R20

Front Left Side: Ginstin 6 mm

Rear Left Side: Ginstin 6 mm

Front Right Side: Ginstin 6 mm

Rear Right Side: Ginstin 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,965.04	5,100.25	16,864.79	76.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,810.00	3,090.00	63.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,865.04	6,910.25	19,954.79	74.28
Approved Total (Overridden) (S\$)		5,500.00		

(S\$)	26,865.04	5,500.00	21,365.04	79.53
+ GST 7.00/7.00% (S\$)	1,880.55	385.00	1,495.55	79.53
Nett Amount (S\$)	28,745.59	5,885.00	22,860.59	79.53
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/02/2021

Date Inspected: 23/02/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Oct 2021)	
Parts:	N/A	MITSUBISHI FV517JD2RDEB 11.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XB7439C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,450.00 FL	*- FL
2	1		*FRONT O/S CORNER PANEL	Serviceable	600.00 FL	*- FL
3	1		*FRONT O/S DOOR	Distorted	14,600.00 FL	*5,883.87 FL
4	1		*FRONT O/S DOOR LAMP	Not Necessary	250.00 FL	*- FL
5	1		*FRONT O/S DOOR STEP PANEL	Not Necessary	650.00 FL	*- FL
6	1		*FRONT O/S DOOR LOCK	Not Necessary	745.60 FL	*- FL
7	1		*FRONT O/S DOOR CATCH	Not Necessary	220.00 FL	*- FL
8	1		*FRONT O/S WHEEL ARCH PANEL GARNISH	Cracked	680.00 FL	*237.19 FL
9	1		*FRONT O/S WHEEL ARCH GARNISH	Cut	410.00 FL	*210.60 FL
10	1		*FRONT O/S DOOR COMPANY STICKER	Necessary	450.00 FS	*150.00 FS
11	1		*FRONT O/S CABIN PANEL (NPA)	Repair	0.00 FL	*- FL
12	1		*FRONT O/S FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT O/S STEP PANEL	Not Necessary	1,200.00 FL	*- FL
14	1		*FRONT O/S STEP PANEL GARNISH	Cracked	800.00 FL	*268.68 FL
15	1		*FRONT O/S ALUMINIUM STEP	Not Necessary	300.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,355.60	6,750.34
- List Item Discount on L Items 10.00/25.00% (\$\$)	2,390.56	1,650.09
Total Parts (\$\$)	21,965.04	5,100.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	3,000.00	1,000.00
2	TO SPRAY PAINTING	New	1,400.00	750.00
3	TO REMOVE & REPLACE O/S DOOR	New	400.00	60.00
4	TO RE-SEAL ANTI-RUST	New	100.00	0.00
Gross Labour Cost (S\$)			4,900.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >