

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Ryder Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$8500
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: XB 7439C yr Regn: 27 DEC 2001
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 2RDEB
 Make: Mit FV517JD cc 11945
 Colour: white A/C: Insured / Std / NI / NA
 Sp Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FV517JA001.38
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 11.00 R 20
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or GINSTIN
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 23-02-21
 Survey held at W/S 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Int
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Call: 2577

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Photo (\$)

Survey Fee:

Transportation: _____

Photos _____

Other _____

Print

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : XB7439C

Model: MITSUBISHI FV517
(27/12/2001)

Accident Date : 23/3/2020

Location : QUEENSWAY TOWARDS FARRER ROAD ON LANE 2

3P: GBK4017U (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper X Repair	3,450.00		
2	1 pc	Front o/s corner panel X	600.00		
3	1 pc	Front o/s door / Pig.	14,600.00		
4	1 pc	Front o/s door lamp X	250.00		
5	1 pc	Front o/s door step panel X	650.00		
6	1 pc	Front o/s door lock X	745.60		
7	1 pc	Front o/s door catch X	220.00		
8	1 pc	Front o/s wheel arch panel garnish / CRA	680.00		
9	1 pc	Front o/s wheel arch garnish / CRG	410.00		
10	1 pc	Front o/s door company sticker / REC.		450.00	
11	1 pc	Front o/s cabin panel (repair)			
12	1 pc	Front o/s floor panel (repair)			
13	1 pc	Front o/s step panel X NN	1,200.00		
14	1 pc	Front o/s step panel garnish / CRA	800.00		
15	1 pc	Front o/s aluminium step X NN	300.00		
		Sub-Total:	23,905.60	450.00	0.00
			10%	0%	10%
		After Less %:	21,515.04	450.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		3,000.00	
2		To spray painting.		1,400.00	
3		To remove & replace o/s door.		400.00	
4		To re-seal anti-rust.		100.00	
		Sub-Total:		4,900.00	
		Total:		26,865.04	
		After Less 20%:		21,492.03	

X
X
5882.87
X
X
X
X
237.19
210.6
150
X
268.68
X
6600.34
25% = 4950.25
1000
750
60
X NN

6 Days.
(unpin repair)

23/2/2021

6910.25

20% = 5500

After repair photos.

Guo Qiang - 82880282

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE
S T R

AL 8778 1999
24 hr accident call

Mobil 1

