

## ESTIMATE OF REPAIR

Veh# : XB7439C

Model: MITSUBISHI FV517  
(27/12/2001)

Accident Date : 23/3/2020

Location : QUEENSWAY TOWARDS FARRER ROAD ON LANE 2

3P: GBK4017U (III)

| S/Nos. | Qty  | Description                                       | List \$   | S/Nett \$ | Nett \$ |
|--------|------|---------------------------------------------------|-----------|-----------|---------|
| 1      | 1 pc | Front bumper X Repair                             | 3,450.00  |           |         |
| 2      | 1 pc | Front o/s corner panel X SVC                      | 600.00    |           |         |
| 3      | 1 pc | Front o/s door / P/S.                             | 14,600.00 |           |         |
| 4      | 1 pc | Front o/s door lamp X                             | 250.00    |           |         |
| 5      | 1 pc | Front o/s door step panel X                       | 650.00    |           |         |
| 6      | 1 pc | Front o/s door lock X                             | 745.60    |           |         |
| 7      | 1 pc | Front o/s door catch X                            | 220.00    |           |         |
| 8      | 1 pc | Front o/s wheel arch panel garnish / CRA          | 680.00    |           |         |
| 9      | 1 pc | Front o/s wheel arch garnish / Cont.              | 410.00    |           |         |
| 10     | 1 pc | Front o/s door company sticker / REC.             |           | 450.00    |         |
| 11     | 1 pc | Front o/s cabin panel (repair)                    |           |           |         |
| 12     | 1 pc | Front o/s floor panel (repair)                    |           |           |         |
| 13     | 1 pc | Front o/s step panel X NN                         | 1,200.00  |           |         |
| 14     | 1 pc | Front o/s step panel garnish / CRA                | 800.00    |           |         |
| 15     | 1 pc | Front o/s aluminium step X NN                     | 300.00    |           |         |
|        |      | Sub-Total:                                        | 23,905.60 | 450.00    | 0.00    |
|        |      |                                                   | 10%       | 0%        | 10%     |
|        |      | After Less %:                                     | 21,515.04 | 450.00    | 0.00    |
|        |      | <b>Labour</b>                                     |           |           |         |
| 1      |      | To dismantle damaged parts, straighten & welding. |           | 3,000.00  |         |
| 2      |      | To spray painting.                                |           | 1,400.00  |         |
| 3      |      | To remove & replace o/s door.                     |           | 400.00    |         |
| 4      |      | To re-seal anti-rust.                             |           | 100.00    |         |
|        |      | Sub-Total:                                        |           | 4,900.00  |         |
|        |      | Total:                                            |           | 26,865.04 |         |
|        |      | After Less 20%:                                   |           | 21,492.03 |         |

X  
X  
5883.87  
X  
X  
X  
X  
237.19  
210.6  
150  
X  
268.68  
X  
6600.34  
25%: 4950.25  
1000  
750  
60  
X NN

Chan San Choon  
Director  
DipEng, AAE MIMI,MSAE(Aust)

6 Days.  
(imp sm repair)

23/2/2021

6910.25

20% = 5500

After repair photos.

Guo Qiang - 82880282

**LINK Auto Consultants hence notify the Repainer of the following:**

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer  
Signature:  
Date:

SAFE 8778 1999  
24 hr accident call

Mobil 1

