

Veron Chen (LKKAUTO)

From: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Sent: Wednesday, 17 March 2021 4:04 PM
To: Veron Chen (LKKAUTO); SUR
Subject: RE: SMD 9481K-DOA: 11/2/21 (AIG REF: 7297776970SG)

Hi Veron,

Resurvey photos by Adrian has identify torn corner tab for the Front Bumper, hence please proceed with the replacement.

Thank you

Best Regards,

Lim Kok Chong
Senior Motor Surveyor
AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, Level 10
Singapore 079120
Mobile +(65) 8876 5437
Kok-Chong.Lim@aig.com | www.aig.com.sg

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Wednesday, March 17, 2021 2:55 PM
To: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; SUR <sur@lkkauto.com>
Subject: [EXTERNAL] SMD 9481K-DOA: 11/2/21 (AIG REF: 7297776970SG)

This message is from an external sender; be cautious with links and attachments.

Dear Kok Chong,

Refer to Front Bumper to repair instead of Renew.

Please see photos uploaded in merimen.

Premium request replacement for front bumper.

For your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.