



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3357R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	CRACKED	430.90	430.90
1	FRONT BUMPER BRACKET LH	CRACKED	35.00	35.00
1	FRONT BUMPER CENTRE MOULDING	SERVICEABLE	368.50	-
1	HEAD LAMP ASSY LH	CRACKED	1,993.65	1,993.65
1	FRONY DAY LIGHT LH	SERVICEABLE	642.50	-
1	FRONT SIDE GRILLE LH	SCRATCHED	186.90	186.50
	LESS 20% DISCOUNT		-731.49	-529.21
			2,925.96	2,116.84
<u>LABOUR</u>				
	PANEL BEATING.		700.00	350.00
	SPRAY PAINT.		600.00	500.00
	CHECK LIGHTING.		60.00	30.00
			1,360.00	880.00
GRAND TOTAL			4,285.96	2,996.84
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,996.84

Report Ref No. NS/INC21002421/Nqf3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.