

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS3/INC21002426/Qqf3e2	
	73 BRAS BASAH R #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	29/03/2021	
	ATTN: ENG HUEY	HUEY	Code:	INC	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJE 1667A	Veh. Inspected	SLK 3287U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1121607-001	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	21/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ C 180	c.c	1597	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	WDD2040452A595897	Colour	WHITE	
	Odometer	210267 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/40Z R18	FALKEN	6 mm	
	L/H Front Tyre	245/40Z R18	FALKEN	6 mm	
	R/H Rear Tyre	245/40Z R18	FALKEN	6 mm	
	L/H Rear Tyre	245/40Z R18	FALKEN	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S			
5.	General Information				
	Accident Date	18/02/2021	Inspect Date / Time	23/02/2021 ( 11:21 AM )	
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC21002426/Qqf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser