



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 8674L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RH DOOR	BUCKLED	2,439.42	2,439.42
	LESS 5% DISCOUNT		-121.97	-121.97
			2,317.45	2,317.45
1	RH REAR ALLOY RIM (SN)	CUT	1,280.66	500.00
	LESS 5% DISCOUNT		-64.03	-
			1,216.63	500.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDERIES (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<b><u>LABOUR</u></b>			
	TUFF KOTE.	NOT NECESSARY	25.00	-
	REMOVE AND REFIT RH DOOR,RH REAR ALLOY RIM,PANEL-BEAT RH REAR FENDER,SIDE SKIRT,REAR BUMPER AND OTHER ASSOCIATED COMPONENTS.		560.00	400.00
	SURFACE PREPARATION,SPRAY PAINT AND POLISH RH DOOR,REAR FENDER,SIDE SKIRT,REAR BUMPER AND OTHER AFFECTED AREAS.		1,000.00	800.00
	REMOVE,BALANCE AND REFIT RH REAR ALLOY RIM.		25.00	20.00
	CHECK AND ADJUST REAR WHEEL ALIGNMENT.		100.00	60.00
	DIAGNOSTIC CHECK AND ERASE FAULT CODES AFTER THE REPAIR.	NOT NECESSARY	80.00	-
			1,790.00	1,280.00
<b>GRAND TOTAL</b>			<b>5,374.08</b>	<b>4,097.45</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,250.00</b>

Report Ref No. CS/INC21002429/Gtf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.