



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4202H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER ASSY -RR BUMPER	TO REPAIR SEE LABOUR	1,106.00	-
1	MOULDING ASSY -SIDE SILL R	DEFORMED	732.80	732.80
1	PANEL ASSY-RR DR RH	TO REPAIR SEE LABOUR	2,201.10	-
1	CAP ASSY -WHEEL HUB	DEFORMED	217.20	217.20
	LESS 20% DISCOUNT		-851.42	-190.00
			3,405.68	760.00
	<u>SPECIAL NETT ITEMS</u>			
1	APP LOGO REAR DOOR L/R CT (SN)	NECESSARY	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER ASSY -RR BUMPER AND PANEL ASSY -RR DR RH .		900.00	560.00
	TRANSFER DOOR PART.	NOT NECESSARY	120.00	-
	RENEW ADVERTISEMENT STICKER-BUMPER .	NOT NECESSARY	50.00	-
	RENEW ADVERTISEMENT STICKER -DOOR .		100.00	100.00
	RENEW ADVERTISEMENT STICKER -FENDER .		200.00	100.00
	RENEW ADVERTISEMENT STICKER -ROCKET.		100.00	100.00
	SPRAYPAINT CHARGE.		1,200.00	1,000.00
			2,670.00	1,860.00
GRAND TOTAL			6,155.68	2,700.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CC3/QW21002430/Nea3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.