

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002439/GTF3E2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800120904
Claimant Vehicle No :	SLB3764G	Insured Vehicle No :	SME3985H
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	2533167382SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB3764G	Engine No:	2NR8501149
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (A)	Chassis No:	NRE1610009749
Reg. Date:	04/04/2016 (Man. Year: 2015)	Odometer:	203544 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/02/2021	Gee Seng Motor Service (HQ)
Date Inspected:	23/02/2021 Inspected At:	Blk 1 Kaki Bukit Ave 6, #01-69 Autobay @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Buckled	0.00 F	*- F
2	1		*REAR LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
3	1		*REAR LH DOOR RUBBER	Cut	0.00 F	*- F
4	1		*REAR LH DOOR LOCK	Bent	0.00 F	*- F
5	1		*REAR LH DOOR INNER TRIM BOARD	Cracked	0.00 F	*- F
6	1		*REAR BUMPER BRACKET	Cut	0.00 F	*- F
7	1		*REAR BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
8	1		*REAR BUMPER REFLECTOR	Necessary	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
10	1		*REAR LH FENDER	Buckled	0.00 F	*- F
11	1		*REAR LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
12	1		*STICKER	Necessary	0.00 F	*- F
13	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
14	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
15	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >