

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21002440/EBS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMS8556G	Insured Vehicle No :	SMA6716U
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000718

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8556G		
Make & Model:	MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A)	Engine No:	26492080024177
Reg. Date:	19/03/2020 (Man. Year: 2019)	Chassis No:	WDD2130802A749389
Colour:	Blue	Odometer:	6524 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,915.10	3,520.82	1,394.28	28.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	2,060.00	1,560.00	43.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,535.10	5,580.82	2,954.28	34.61
+ GST 7.00/7.00% (S\$)	597.46	390.66	206.80	34.61

Nett Amount (S\$)	9,132.56	5,971.48	3,161.08	34.61
+ Car Rental (3.0 x S\$170.00/day + 7.00% GST) (S\$)		545.70		
Nett Liability (S\$)		6,517.18		

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
 188 Pandan Loop
 Singapore 128378

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2021)
Parts:	143	MERCEDES-BENZ E200 AVG 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS8556G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/FRONT BUMPER MOUNTING RAIL	Not Necessary	9.14 FS	*- FS
2	1		*LH/BASIC MOUNTING FOR BUMPER	Not Necessary	68.36 FS	*- FS
3	1		*LH/HEADLAMP UNIT	Cut	3,520.82 FS	*3,520.82 FS
4	1		*FRONT BUMPER	Not Necessary	1,316.78 FS	*- FS
					Total Parts (S\$)	4,915.10
						3,520.82

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUSTOMER REQUEST	New	1,920.00	960.00
2	DISASSEMBLE AND REPAIR FRONT BUMPER & REFINISH	New	1,200.00	600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	TO REMOVE ,REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
Gross Labour Cost (\$\$)			3,620.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >