

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21002444/GVF3E2

Date: 26/03/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000127		
Claimant Vehicle No :	SHD6989S	Insured Vehicle No :	SLK5912K		
Date of Loss:	19/02/2021	Nature of Claim:	TP	Claim No:	M2100884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6989S	Engine No:	G4LEKU409089
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU188030
Reg. Date:	30/09/2020 (Man. Year: 2019)	Odometer:	71715 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,553.44	5,337.48	2,215.96	29.34
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,300.00	2,010.00	290.00	12.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,864.44	7,358.48	2,505.96	25.40
+ GST 7.00/7.00% (S\$)	690.51	515.09	175.42	25.40
Nett Amount (S\$)	10,554.95	7,873.57	2,681.38	25.40

INSPECTION

Date of Assignment:	22/02/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/02/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2021)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6989S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID COVER	Buckled	2,480.40 FL	-	*2,480.40 FL
2	1		*BOOTLID LOCK UPPER	Bent	224.00 FL	-	*224.00 FL
3	1		*BOOTLID EMBLEM - IONIQ	Necessary	31.30 FL	-	*31.30 FL
4	1		*BOOTLID EMBLEM - HYBRID	Necessary	24.30 FL	-	*24.30 FL
5	1		*BOOTLID EMBLEM - H	Not Necessary	28.00 FL	-	*- FL
6	1		*ANTENNA ASSY - SMARTK	Damaged	40.50 FL	-	*40.50 FL
7	1		*REAR SPOILER	Not Necessary	665.40 FL	-	*- FL
8	1		*BOOTLID COMFORTDELGRO LOGO	Necessary	30.00 F	-	*30.00 FS
9	1		*BOOTLID COMFORTDELGRO TEL.NO LOGO	Necessary	30.00 FL	-	*30.00 FS
10	1		*BOOTLID APPS LOGO	Necessary	40.00 FL	-	*40.00 FS
11	1		*BOOTLID LAMP LH	Cut	794.40 FL	-	*794.40 FL
12	1		*TAILLAMP ASSY LH	Not Necessary	870.40 FL	-	*- FL
13	1		*LICENCE LAMP LH	Distorted	85.30 FL	-	*85.30 FL
14	1		*LICENCE LAMP RH	Not Necessary	85.30 FL	-	*- FL
15	1		*REAR NUMBER PLATE	Cracked	25.00 FL	-	*25.00 FS
16	1		*REAR BUMPER	Deformed	459.40 FL	-	*459.40 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	-	*394.80 FL
18	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	138.10 FL	-	*138.10 FL
19	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	-	*- FL
20	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	55.80 FL	-	*- FL
21	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
22	1		*BOOTLID LAMP LH	Repeated	794.40 FL	-	*- FL
23	1		*REAR BUMPER CENTRE UNDER COVER	Deformed	225.00 FL	-	*225.00 FL
24	1		*REAR BUMPER FOG LAMP	Cracked	201.50 FL	-	*201.50 FL
25	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	-	*- FL
26	1		*REVERSE SENSOR	Damaged	180.00 F	-	*180.00 FS
27	1		*REAR BUMPER MAT	Deformed	50.00 F	-	*50.00 FS
28	1		*REAR BUMPER CENTRE COVER	Cracked	123.85 FL	-	*123.85 FL
29	1		*REAR END PANEL	Buckled	532.00 FL	-	*532.00 FL
30	2		*WINDSCREEN SEALANT	Not Necessary	46.00 F	-	*- FS

Supplementary #1

31	1		*MOULDING ASSY - REAR BUMPER COVER	Broken	451.25 FL	-	*451.25 FL
----	---	--	------------------------------------	--------	-----------	---	------------

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,365.30	6,583.10
- List Item Discount on L Items 20.00/20.00% (\$)	1,811.86	1,245.62
Total Parts (\$)	7,553.44	5,337.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	1,050.00
2	SPRAYPAINT	New	800.00	750.00
3	WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	REMOVE/REFIX REVEESE SENSOR	New	80.00	40.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
			Gross Labour Cost (\$\$)	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >