

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21002446/R1vf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	03/03/2021	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 3653B	Veh. Inspected	SJW 4018J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	20/21/21/VC00/024210	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	22/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.3G A	c.c	1339	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	GE61144552	Colour	RED	
	Odometer	117008 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/65 R14	DUNLOP	5 mm	
	L/H Front Tyre	185/65 R14	DUNLOP	5 mm	
	R/H Rear Tyre	185/65 R14	DUNLOP	5 mm	
	L/H Rear Tyre	185/65 R14	DUNLOP	5 mm	
4.	. Description of Damages				
	THE VEHICLE SUS	JSTAINED DAMAGES AT THE O/S BODY.			
5.	5. General Information				
	Accident Date	04/02/2021	Inspect Date / Time	22/02/2021 (05:29 PM)	
	Survey held at	WILLY MOTOR COMPANY			
		27A JURONG PORT ROAD #01-32 SINGAPORE 619101			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21002446/R1vf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser