



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2201343

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/03/2022
Reference CC4/LPC21002459/Upa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 2615Z
Insured Veh. XA 8988H
Claim No. 20/21/21/VC05/024254
Policy No. Z20VC5005650
Accident Date 19/02/2021
Inspection Date 22/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21002459/Upa3q2 Date: 14/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XA 8988H	Veh. Inspected	GBC 2615Z	
Policy No.	Z20VC5005650	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024254	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	22/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN (M)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JN1MG4E25Z0795931	Colour	SILVER	
Odometer	237518 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	NEUTON	6 mm	
L/H Front Tyre	195 R15	NEUTON	6 mm	
R/H Rear Tyre	195 R15	NEUTON	6 mm	
L/H Rear Tyre	195 R15	NEUTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2021	Inspection Date	22/02/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 2615Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	899.00	629.10
1	FRONT BUMPER BEAM	NOT NECESSARY	322.00	-
1	FRONT BUMPER SIDE RETAINER N/S	BENT	65.00	65.00
1	SET FRONT BUMPER CLIPS	NECESSARY	38.00	38.00
1	FRONT BUMPER FOG LAMP N/S	NOT NECESSARY	322.40	-
1	FRONT BUMPER FOG LAMP GARNISH N/S	GRAZED	166.80	120.70
1	HEADLAMP N/S	CRACKED	750.50	486.20
1	FRONT SIGNAL LAMP N/S	BROKEN	288.20	165.20
1	FRONT DOOR N/S	BADLY DENTED	1,655.90	1,315.20
2	FRONT DOOR HINGES @\$101.00	BENT	202.00	190.00
1	FRONT DOOR CHECKER N/S	SERVICEABLE	151.00	-
1	FRONT DOOR INNER RUBBER N/S	NECESSARY	188.20	161.20
1	FRONT DOOR INNER LOCK N/S	SHORTED	315.00	288.50
1	FRONT DOOR INNER TRIM BOARD N/S	DEFORMED / CRACKED	650.00	366.20
1	SET FRONT DOOR INNER TRIM BOARD CLIPS N/S	NECESSARY	38.00	38.00
1	FRONT DOOR GLASS REGULATOR & MOTOR N/S	BENT / JAMMED	305.90	305.90
1	FRONT DOOR OUTER PILLAR N/S	DENTED / BENT	1,185.20	1,185.20
1	FRONT DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	188.50	-
1	FRONT STEP PANEL N/S	DISTORTED	350.00	312.30
1	FRONT STEP PANEL GARNISH N/S	DISTORTED	388.20	366.50
1	FRONT CORNER PANEL N/S	DISTORTED	615.00	492.50
1	FRONT WHEEL ARCH PANEL N/S	DENTED / WARPED	545.80	525.30
1	FRONT WHEEL ARCH PANEL GARNISH N/S	NOT NECESSARY	122.90	-
1	CMIRROR N/S	NOT NECESSARY	560.20	-
1	FRONT DOOR OUTER HANDLE N/S	GRAZED	244.80	244.80
1	FRONT DOOR OUTER REAR PILLAR N/S	DENTED / BENT	588.20	588.20
1	SLIDING DOOR N/S	BENT / WARPED	1,688.20	1,545.20
1	SLIDING DOOR OUTER HANDLE N/S	GRAZED	285.80	240.80
1	REAR FENDER N/S	DISTORTED / CRACKED	2,650.20	2,010.30

Report Ref No. CC4/LPC21002459/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER PANEL N/S	TO REPAIR SEE LABOUR	622.20	-
1	TAILGATE	DISTORTED	1,889.20	1,742.00
1	TAILGATE DAMPER N/S	SERVICEABLE	321.90	-
2	TAILGATE HINGES @\$80.00	N/S TWISTED	160.00	78.00
1	TAILGATE REAR LOGO	NECESSARY	65.20	45.50
1	REAR WINDSCREEN	SHATTERED	1,455.60	950.20
1	REAR BUMPER	NOT NECESSARY	741.20	-
	LESS 10% DISCOUNT		-	-1,449.60
			21,026.20	13,046.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR FENDER 'LALAMOVE' STICKER (SN)	NOT NECESSARY	420.00	-
1	SET TAILGATE 'LALAMOVE' STICKER (SN)	NOT NECESSARY	350.00	-
1	TAILGATE '70KM/H' STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	FRONT WHEEL HUP CAP N/S (SN)	TO REPAIR SEE LABOUR	220.00	-
			1,160.00	130.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO CONDUCT WHEEL ALIGNMENT .		120.00	60.00
	TO TRANSFER FRONT DOOR MECHANISM .		100.00	60.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN .		150.00	100.00
	TO DISMANTLE & REFIX FRONT DASHBOARD .		280.00	180.00
	TO DISMANTLE & REFIX SLIDING DOOR MECHANISM .		100.00	50.00
	TO DISMANTLE & REPLACED REAR WINDSCREEN .		150.00	100.00
	TO TRANSFER TAILGATE MECHANISM .		100.00	50.00
	TO SPRAY RUST PROOFING .		150.00	120.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS .INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL N/S AND FRONT WHEEL HUP CAP N/S .		2,200.00	1,600.00

Report Ref No. CC4/LPC21002459/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING .		2,000.00	1,400.00
			5,400.00	3,750.00
GRAND TOTAL			27,586.20	16,926.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,500.00

Report Ref No. CC4/LPC21002459/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 2615Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 2615Z

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 2615Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

