

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21002470/UTF3Q2

Date: 10/03/2021

### REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG21001003
Claimant Vehicle No :	SDX8832P	Insured Vehicle No :	GBJ1403M
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	CDMCG21000331

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDX8832P	Engine No:	27186030044628
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120472A186621
Reg. Date:	06/08/2010 (Man. Year: 2010)	Odometer:	97328 km
Colour:	Brown		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,188.40	4,522.00	666.40	12.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,335.00	1,350.00	985.00	42.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,523.40</b>	<b>5,872.00</b>	<b>1,651.40</b>	<b>21.95</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,650.00</b>		
<b>(\$\$)</b>	7,523.40	4,650.00	2,873.40	38.19
<b>+ GST 7.00/7.00% (\$\$)</b>	526.64	325.50	201.14	38.19
<b>Nett Amount (\$\$)</b>	<b>8,050.04</b>	<b>4,975.50</b>	<b>3,074.54</b>	<b>38.19</b>

### INSPECTION

Date of Assignment:	22/02/2021	Present Location:	Specialists Motor Pte Ltd (HQ)
Date Inspected:	01/03/2021	Inspected At:	Specialists Motor Pte Ltd (HQ)
			Blk 3018A Ubi Road 1, #01-24/25/26
			Singapore 408711
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/10/2021

Adjuster Report

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2021)
<b>Parts:</b>	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDX8832P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BONNET</b> (WCP)	Dented	1,500.00 F	*1,500.00 F
2	1		<b>*FRONT BONNET EMBLEM</b> (WCP)	Not Necessary	45.00 F	*- F
3	1		<b>*FRONT BONNET SPRING</b> O/S (WCP)	Missing	40.00 F	*40.00 F
4	1		<b>*FRONT BONNET INSULATION SHIELD CLIPS</b> (WCP)	Not Necessary	50.00 F	*- F
5	1		<b>*FRONT GRILLE ASSY</b> (WCP)	Cracked	870.00 F	*870.00 F
6	1		<b>*HEADLAMP ASSY LH</b> (WCP)	Cracked	510.00 F	*510.00 F
7	1		<b>*FRONT RADIATOR TOP GARNISH</b> (WCP)	Not Necessary	60.00 F	*- F
8	1		<b>*FRONT RADIATOR TOP GARNISH CLIP</b> (WCP)	Not Necessary	30.00 F	*- F
9	1		<b>*FRONT BUMPER FASCIA</b> (WCP)	Dented/Deformed	680.00 F	*680.00 F
10	1		<b>*FRONT BUMPER CLIPS</b> (WCP)	Necessary	30.00 F	*30.00 F
11	2		<b>*FRONT BUMPER SIDE RETAINER L&amp;RH</b> (WCP)	Not Necessary	56.00 F	*- F
12	2		<b>*FRONT BUMPER BRACKET L&amp;RH</b> (WCP)	Not Necessary	86.00 F	*- F
13	1		<b>*FRONT BUMPER SPONGE (CENTRE)</b> (WCP)	Not Necessary	60.00 F	*- F
14	2		<b>*FRONT BUMPER SPONGE L&amp;RH</b> (WCP)	Not Necessary	60.00 F	*- F
15	1		<b>*FRONT NUMBER PLATE GARNISH</b> (WCP)	Bent	90.00 F	*90.00 F
16	2		<b>*FRONT BUMPER CHROME L&amp;RH</b> (WCP)	Not Necessary	100.00 F	*- F
17	1		<b>*FRONT NUMBER PLATE</b>	Bent	50.00 FS	*40.00 FS
<b>Supplementary #1</b>						
18	1		<b>*FRONT GRILLE SUPPORT</b> (WCP)	Cracked	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>4,332.00</b>	<b>3,775.00</b>
<b>+ Margin on L,N Items 20.00/20.00% (\$)</b>	856.40	747.00
<b>Total Parts (\$)</b>	<b>5,188.40</b>	<b>4,522.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT, RENEW, KNOCKING & WELDING FRONT BONNET, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY	New	980.00	600.00
2	TUFF-KOTE ON DAMAGE PARTS	New	40.00	30.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,280.00	700.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,335.00</b>	<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >