



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2764X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR RH SIDE GATE (N) (CONSISTENT)	TO REPAIR SEE LABOUR	2,600.60	-
1	REAR RH SIDE GATE LOWER LOCK CATCH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	85.10	-
1	REAR RH SIDE LOWER RUBBER STOPPER BRACKET (N) (CONSISTENT)	BENT	183.40	183.40
1	SET REAR RH SIDE LOWER RUBBER STOPPER (N) (CONSISTENT)	MISSING	14.00	14.00
1	REAR TAILGATE (N) (CONSISTENT)	BENT	1,399.70	1,399.70
1	REAR TAILGATE 'NISSAN' EMBLEM (N) (CONSISTENT)	NECESSARY	125.60	125.60
1	RH TAILLAMP BRACKET (N) (CONSISTENT)	BENT	57.40	57.40
1	RH TAILLAMP (N) (CONSISTENT)	CRACKED	148.70	148.70
1	REAR NUMBER PLATE BRACKET (N) (CONSISTENT)	TO REPAIR SEE LABOUR	48.50	-
1	REAR DECK END PANEL (N) (CONSISTENT)	BENT	848.60	688.00
	LESS 10% DISCOUNT		-551.16	-261.68
			4,960.44	2,355.12
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR RH SIDE GATE COMPANY STICKER (SN) (CONSISTENT)	NOT NECESSARY	350.00	-
1	REAR TAILGATE INNER METAL PROTECTION PANEL (SN) (CONSISTENT)	NECESSARY	450.00	300.00
1	REAR TAILGATE LH '70KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	15.00	12.00
1	REAR TAILGATE RH '13 PAX' STICKER (SN) (CONSISTENT)	NECESSARY	15.00	12.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	45.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	280.00	-
			1,155.00	324.00
<b>LABOUR</b>				
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES .INCLUSIVE OF THE REPAIR OF REAR RH SIDE GATE ,REAR RH SIDE GATE LOWER LOCK CATCH AND REAR NUMBER PLATE BRACKET .		1,000.00	700.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES.		1,000.00	600.00
	TO CHECK WIRING & LIGHTINGS .		40.00	20.00
	TO REPLACE & RE-INSTALL REVERSE SENSORS .		80.00	50.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT .		80.00	60.00
			2,200.00	1,430.00
	<b>GRAND TOTAL</b>		<b>8,315.44</b>	<b>4,109.12</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,250.00</b>

Report Ref No. CC4/ASM21002472/Kps3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.