

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21002473/T1VF3E2

**Date:** 19/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100456052  
Claimant Vehicle No : SGU7499E Insured Vehicle No : SLA7233B  
Date of Loss: 18/02/2021 Nature of Claim: TP Claim No: 0598769578SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU7499E**  
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2851521  
Reg. Date: 24/05/2007 (Man. Year: 2007) Chassis No: ZNE100366539  
Colour: Silver Odometer: 352842 km  
Engine Capacity: 1794 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: CST 6 mm Rear Left Side: CST 6 mm  
Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 22/02/2021  
Date Inspected: 22/03/2021 Inspected At: Yap Lee Motor (HQ)  
1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F	
2	1		*REAR BUMPER	Deformed	0.00 F	*- F	
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
4	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F	
5	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F	
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F	
7	1		*REAR END PANEL	Bent	0.00 F	*- F	
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F	
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F	
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F	
11	1		*TAILGATE	Bent	0.00 F	*- F	
12	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
13	1		*TAILGATE OUTER HANDLE	Cracked	0.00 F	*- F	
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F	
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F	
16	1		*TAILGATE LOCK	Bent	0.00 F	*- F	
17	1		*TAILGATE RUBBER	Cut	0.00 F	*- F	
18	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F	
19	1		*SPARE TYRE BRACKET	* Check	0.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**