

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002474/R1TF3E2

Date: 15/09/2021

REFERENCE

Insured/Claimant:	KOH BOON HOW	Policy No:	1700073271		
Date of Loss:	17/02/2021	Nature of Claim:	OD	Claim No:	6685407703SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL1802R	Engine No:	CVK047056
Make & Model:	AUDI A5, 1.8 SPORTBACK (A)	Chassis No:	WAUZZZF50JA034274
Reg. Date:	16/11/2017 (Man. Year: 2017)	Odometer:	69585 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$127,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,105.30	13,830.64	26,274.66	65.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,532.00	4,402.00	12,130.00	73.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,637.30	18,232.64	38,404.66	67.81
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	54,837.30	16,432.64	38,404.66	70.03
+ GST 7.00/7.00% (S\$)	3,838.61	1,150.28	2,688.33	70.03
Nett Amount (S\$)	58,675.91	17,582.92	41,092.99	70.03

INSPECTION

Date of Assignment:	22/02/2021		
Date Inspected:	22/02/2021	Inspected At:	281 Alexandra Road
Estimated Period of Repair:	8.0 days		Repairer : Premium Automobiles Pte Ltd (HQ)

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER LOWER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	228.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Scratched	535.00 FS	*428.00 FS
7	1		*FRONT AIR DUCT LH	Not Necessary	63.00 FS	*- FS
8	1		*FRONT AIR DUCT RH	Not Necessary	63.00 FS	*- FS
9	1		*FRONT RADIATOR GRILLE	Cracked	2,326.00 FS	*1,860.80 FS
10	1		*FRONT MOUNT BRACKET LH	Not Necessary	51.00 FS	*- FS
11	1		*FRONT MOUNT BRACKET RH	Not Necessary	51.00 FS	*- FS
12	1		*FRONT COVER FOR RADIATOR GRILLE UPPER	Not Necessary	189.00 FS	*- FS
13	1		*FRONT OUTER AIR GUIDE GRILLE LH	Not Necessary	474.00 FS	*- FS
14	1		*FRONT OUTER AIR GUIDE GRILLE RH	Not Necessary	474.00 FS	*- FS
15	2		*FRONT OUTER SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
16	2		*FRONT INNER SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
17	4		*INNER PARK SEAL SENSOR	Not Necessary	14.00 FS	*- FS
18	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
19	1		*FRONT BUMPER CARRIER FOAM FILLER PIECE	Deformed	124.00 FS	*99.20 FS
20	1		*FRONT BUMPER COVER SIGHT SHIELD	Cracked	127.00 FS	*101.60 FS
21	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	36.00 FS	*- FS
22	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	36.00 FS	*- FS
23	1		*FRONT BUMPER BRACKET LH	Not Necessary	214.00 FS	*- FS
24	1		*FRONT BUMPER BRACKET RH	Not Necessary	214.00 FS	*- FS
25	1		*CAUTION LABEL	Necessary	14.00 FS	*10.88 FS
26	1		*AIRCON LABEL	Necessary	8.00 FS	*5.68 FS
27	1		*FRONT CARRIER BRACKET	Cracked	137.00 FS	*109.60 FS
28	1		*FRONT BUMPER SUPPORT BRACKET LH	Not Necessary	29.00 FS	*- FS
29	1		*FRONT BUMPER SUPPORT BRACKET RH	Not Necessary	29.00 FS	*- FS
30	1		*HIGH TONE HORN LH	Not Necessary	126.00 FS	*- FS
31	1		*HIGH TONE HORN RH	Not Necessary	126.00 FS	*- FS
32	1		*SPRING SHACKLE LH	Not Necessary	29.00 FS	*- FS
33	1		*SPRING SHACKLE RH	Not Necessary	29.00 FS	*- FS
34	1		*FRONT BONNET	Buckled	3,312.00 FS	*2,649.60 FS
35	3		*FRONT BUMPER RETAINING CLIP	Necessary	3.30 FS	*2.64 FS
36	6		*FRONT BUMPER SAFETY CATCH NUT	Necessary	24.00 FS	*19.20 FS
37	1		*FRONT BONNET ATTACHMENT PARTS	Necessary	123.00 FS	*98.40 FS
38	2		*FRONT BONNET LID HINGE LH / RH	Not Necessary	419.00 FS	*- FS
39	1		*FRONT BONNET LID HINGE RH	Not Necessary	419.00 FS	*- FS
40	1		*FRONT BUMPER PROTECTION PAD CENTRE	Necessary	28.00 FS	*21.84 FS
41	1		*FRONT BUMPER PROTECTION PAD - LH	Necessary	28.00 FS	*22.00 FS
42	1		*FRONT BUMPER PROTECTION PAD RH	Necessary	28.00 FS	*21.84 FS
43	1		*FRONT BONNET INSULATION PAD	Not Necessary	343.00 FS	*- FS
44	2		*FRONT BONNET STRUT	Not Necessary	241.00 FS	*- FS
45	1		*FRONT BONNET SAFETY CATCH LH	Not Necessary	50.00 FS	*- FS
46	1		*FRONT BONNET SAFETY CATCH RH	Not Necessary	50.00 FS	*- FS
47	1		*FRONT BONNET LID LOCK	Not Necessary	427.00 FS	*- FS
48	1		*FRONT BONNET BOWDEN CABLE CENTRE	Not Necessary	58.00 FS	*- FS
49	1		*FRONT BONNET CABLE COVER	Not Necessary	10.00 FS	*- FS
50	1		*FRONT BONNET RELEASE CABLE	Cut	58.00 FS	*46.00 FS
51	1		*FRONT BONNET RELEASE CABLE HANDLE	Not Necessary	13.00 FS	*- FS
52	1		*LID LOCK CABLE RH	Not Necessary	74.00 FS	*- FS
53	1		*FRONT BUMPER PLENUM CHAMBER COVER	Not Necessary	97.00 FS	*- FS
54	1		*FRONT LED HEADLIGHT LH	Not Necessary	7,902.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRONT LED HEADLIGHT RH	Cracked	7,902.00 FS	*6,321.60 FS
56	1		*PRESSURE CYLINDER LH	Not Necessary	198.00 FS	*- FS
57	1		*PRESSURE CYLINDER RH	Not Necessary	198.00 FS	*- FS
58	1		*HEADLIGHT WASHER HOSE	Not Necessary	86.00 FS	*- FS
59	1		*LOCK CARRIER MOUNTING FOR COOLANT RADIATOR	Not Necessary	1,016.00 FS	*- FS
60	2		*RADIATOR SUPPORT BRACKET	Not Necessary	76.00 FS	*- FS
61	1		*A/C CONDENSER	Not Necessary	622.00 FS	*- FS
62	1		*RADIATOR PRESSURE SENSOR	Not Necessary	191.00 FS	*- FS
63	1		*HIGH PRESSURE VALVE SWITCH	Not Necessary	51.00 FS	*- FS
64	1		*TEMP SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
65	1		*INTER AIR COOLER	Not Necessary	586.00 FS	*- FS
66	4		*READY MIX COOLANT 1.5 LITRE	Not Necessary	95.00 FS	*- FS
67	1		*RADIATOR	Not Necessary	904.00 FS	*- FS
68	1		*OUTER AIR DUCT LH	Not Necessary	32.00 FS	*- FS
69	1		*OUTER AIR DUCT RH	Cracked	31.00 FS	*24.64 FS
70	1		*RADIATOR AIR GUIDE LH	Cracked	16.00 FS	*12.80 FS
71	1		*RADIATOR AIR GUIDE RH	Cracked	16.00 FS	*12.80 FS
72	1		*RADIATOR AIR GUIDE CENTRE	Not Necessary	16.00 FS	*- FS
73	1		*RADIATOR GUIDE LOWER	Cracked	22.00 FS	*17.20 FS
74	1		*ENGINE AIR INTAKE HOSE	Not Necessary	22.00 FS	*- FS
75	1		*AIR GUIDE	Cracked	53.00 FS	*42.40 FS
76	1		*AIR FILTER	Not Necessary	386.00 FS	*- FS
77	1		*INTAKE HOSE	Not Necessary	95.00 FS	*- FS
78	1		*AIR MASS METER	Not Necessary	567.00 FS	*- FS
79	1		*FRONT FENDER WING LH	Not Necessary	1,060.00 FS	*- FS
80	1		*FRONT FENDER WING RH	Not Necessary	1,060.00 FS	*- FS
81	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
82	1		*FRONT FENDER END PLATE LH	Not Necessary	74.00 FS	*- FS
83	1		*FRONT FENDER END PLATE RH	Not Necessary	74.00 FS	*- FS
84	1		*FRONT FENDER BRACKET LH	Not Necessary	35.00 FS	*- FS
85	1		*FRONT FENDER BRACKET RH	Not Necessary	35.00 FS	*- FS
86	1		*FRONT FENDER BRACE LH	Not Necessary	118.00 FS	*- FS
87	1		*FRONT FENDER BRACE RH	Not Necessary	118.00 FS	*- FS
88	1		*FRONT FENDER NAME PLATE LH	Not Necessary	164.00 FS	*- FS
89	1		*FRONT FENDER NAME PLATE RH	Not Necessary	164.00 FS	*- FS
90	1		*FRONT FENDER WHEEL SPOILER LH	Not Necessary	73.00 FS	*- FS
91	1		*FRONT FENDER WHEEL SPOILER RH	Not Necessary	73.00 FS	*- FS
92	1		*FRONT FENDER LINER EXTENSION LH	Not Necessary	35.00 FS	*- FS
93	1		*FRONT FENDER LINER EXTENSION RH	Not Necessary	36.00 FS	*- FS
94	1		*FRONT FENDER STONE CHIP GUARD LH	Not Necessary	51.00 FS	*- FS
95	1		*FRONT FENDER STONE CHIP GUARD RH	Not Necessary	51.00 FS	*- FS
96	1		*FRONT NUMBER PLATE	Scratched	60.00 FS	*60.00 FS
97	1		*SUNDRIES	Necessary	350.00 FS	*41.12 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 40,105.30 13,830.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	280.00	0.00
4	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNITS AND POWER MODULES	New	800.00	250.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	1,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND RHS FRONT DOOR	New	5,100.00	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO DISMANTLE AND RINSTALL LHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL LHS WING MIRROR ASSY (Supplementary)	New	280.00	280.00
9	TO RESPRAY LHS FRONT DOOR AND RHS A-PILLAR UPPER (Supplementary)	New	1,600.00	1,100.00
Gross Labour Cost (\$\$)			16,532.00	4,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >