10/12/21, 4:18 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21002475/R1TF3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 12/10/2021

**REFERENCE** 

Insured/Claimant: CHUA LAY NGOH Policy No: 2070139991

Date of Loss: 10/02/2021 Nature of Claim: OD Claim No: 2179975902SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMV4094H

Make & Model: AUDI A5, 1.8 SPORTBACK (A) Engine No: DEM024876

Reg. Date: 29/09/2020 (Man. Year: 2020) Chassis No: WAUZZZF55LA021281

Colour: White Odometer: 15863 km

Engine Capacity: 1984 cc
Market Value/New Car Price: \$\$177,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,845.00	7,166.00	3,679.00	33.92
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,092.00	5,092.00	4,000.00	43.99
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	19,937.00	12,258.00	7,679.00	38.52
	- Excess (S\$)	3,800.00	3,800.00	0.00	0.00
	(S\$)	16,137.00	8,458.00	7,679.00	47.59
	+ GST 7.00/7.00% (S\$)	1,129.59	592.06	537.53	47.59
	Nett Amount (S\$)	17,266.59	9,050.06	8,216.53	47.59

**INSPECTION** 

Date of Assignment: 22/02/2021

Date Inspected: 22/02/2021 Inspected At: 281 Alexandra Road Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Bent	3,884.00 FS	*3,107.20 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	222.00 FS	*177.60 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*FRONT DOOR CATCH - LH	Necessary	120.00 FS	*96.00 FS
7	1		*FRONT DOOR TRIM - LH	Necessary	164.00 FS	*130.80 FS
8	1		*FRONT DOOR HANDLE TRIM PLATE - LH	Serviceable	88.00 FS	*- FS
9	1		*FRONT DOOR HANDLE HOUSING - LH	Serviceable	8.00 FS	*- FS
10	1		*FRONT DOOR HANDLE COVER - LH	Repair	6.00 FS	*- FS
11	1		*REAR DOOR - LH	Bent	3,884.00 FS	*3,107.20 FS
12	1		*REAR DOOR OUTER SEAL - LH	Necessary	222.00 FS	*177.60 FS
13	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
15	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
16	1		*REAR DOOR CATCH - LH	Necessary	120.00 FS	*96.00 FS
17	1		*REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH	Serviceable	366.00 FS	*- FS
18	1		*SIDE MEMBER TRIM - LH	Serviceable	869.00 FS	*-FS
19	1		*SIDE MEMBER TRIM ATTACHMENT PARTS - LH	Necessary	130.00 FS	*104.00 FS
20	1		*ADHESIVE TAPE FOR SIDE MEMBER TRIM	Necessary	212.00 FS	*169.60 FS
21	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fra	nchise	part. S=Spc	Nett.			
				Total Parts (S\$)	10,845.00	7,166.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	800.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOF AND LHS SILL PANEL TRIM. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL AL PARTS REMOVED		3,600.00	1,500.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL TRIM AND LHS REAR FENDER	New	4,300.00	2,400.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REAPPLY PAINT COATING ON AFFECTED AREA (Supplementary)	New	200.00	200.00
	Gross Lab	our Cost (S\$)	9,092.00	5,092.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >