



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7226J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	1,052.20	1,052.20
1	RADIATOR GRILLE	CUT	1,480.00	1,480.00
1	RADIATOR GRILLE H EMBLEM	NECESSARY	129.50	129.50
1	HEADLAMP LH	BROKEN	1,800.00	1,800.00
1	FRT FENDER LH	TO REPAIR SEE LABOUR	663.00	-
1	FRT BUMPER UPR BRKT LH	NOT NECESSARY	22.40	-
1	FRT BUMPER BRKT LH	NOT NECESSARY	24.60	-
1	FRT BUMPER GRILLE LH	CUT	187.30	187.30
	LESS 20% DISCOUNT		-1,071.80	-929.80
			4,287.20	3,719.20
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT FENDER LH.		600.00	280.00
	SPRAYPAINT-BONNET ETC.		900.00	500.00
	CHECK ALL LIGHTING.		40.00	30.00
	TOWING FEE. (NPA)		-	-
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	40.00	-
			1,580.00	810.00
GRAND TOTAL			5,867.20	4,529.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,600.00

Report Ref No. NS/INC21002478/Gqf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.