LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21002479/EQF3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 22/03/2021

REFERENCE

Insured/Claimant: QUEK BEE SOON,LIONEL Policy No:

Date of Loss: 22/02/2021 Nature of Claim: OD Claim No: 1005293430SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ2075P

 Make & Model:
 KIA CERATO, 1.6 (A)
 Engine No:
 G4FGJH714182

 Reg. Date:
 26/02/2019 (Man. Year: 2018)
 Chassis No:
 KNAF1416MK5025368

Colour: Grey Odometer: 45505 km

Engine Capacity: 1591 cc
Market Value/New Car Price: \$\$74,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Kumho 4 mm Rear Left Side: Kumho 4 mm
Front Right Side: Kumho 4 mm Rear Right Side: Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,546.40	999.20	1,547.20	60.76
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,290.00	900.00	1,390.00	60.70
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,836.40	1,899.20	2,937.20	60.73
	- Excess (S\$)	300.00	300.00	0.00	0.00
	(S\$)	4,536.40	1,599.20	2,937.20	64.75
	+ GST 7.00/7.00% (S\$)	317.55	111.94	205.61	64.75
	Nett Amount (S\$)	4,853.95	1,711.14	3,142.81	64.75

INSPECTION

Date of Assignment: 23/02/2021

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

Date Inspected: 23/02/2021 Inspected At: 209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
3	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
4	1		*GRILLE ASSY-RADIATOR	Not Necessary	223.00 FL	*- FL
5	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
6	1		*MOULDING-FRONT BUMPER, RH	Broken	36.00 FL	*36.00 FL
7	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL
8	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 FL	*14.00 FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Torn	84.00 FL	*84.00 FL
10	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
12	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
13	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
14	1		*LAMP ASSY-HEAD, RH	Not Necessary	1,040.00 FL	*- FL
15	10	and O O N	*CLIP (Supplementary)	Necessary	20.00 FL	*20.00 FL
F=Fra	ıncnıse	part. S=SpcN	ett. L=ListItemDisc.		0.470.00	4.044.00
				Sub Total (S\$)	3,178.00	1,244.00
			- List Item Discount on L	. Items 20.00/20.00% (S\$)	631.60	244.80
				Total Parts (S\$)	2,546.40	999.20
			Report was unsubmitted during	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	RENEW FRT BUMPER. REPAIR / RE-ALIGN RHF FENDER	New	1,400.00	400.00
2	RESPRAY FRT BUMPER & RHF FENDER	New	700.00	350.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEUSING HI-SCAN PRO TEST	ST New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
	Gross	Labour Cost (S\$)	2,290.00	900.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >