



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /QUEK BEE SOON, LIONEL Reg No/Reg Date SMJ2075P / 26/02/201 Date In/Mileage / 0 Chassis No KNAF1416MK5025368 Engine No G4FGJH714182 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/02/2021/ 09:35	BLE	261 / Edwin Caina	29347			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER REPAIR / RE-ALIGN RH FENDER					400			1400.00
E PNT98000 RESPRAY FRT BUMPER & RH FENDER					350			700.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								40.00
M SUNDRY Sundries								20.00
M COVER-FR BUMPER / BR (Black)					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M GRILLE ASSY-RADIATOR ? X NM					1.00	223.00	20.00	178.40
M GARNISH-RADIATOR GRILLE ? X NM					1.00	38.00	20.00	30.40
M MOULDING-FRONT BUMPER, RH / BR (Black)					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, RH / CUT					1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, RH ? X NM bro					1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY ? X NM Torn					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR ? X NM					1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE, MTG ? X NM					1.00	22.00	20.00	17.60
M ORNAMENT-KIA NO.115 / MC					1.00	32.00	20.00	25.60
M BEAM COMPLETE-FR BUMPER ? X NM					1.00	497.00	20.00	397.60
M LAMP ASSY-HEAD, RH ? X NM					1.00	1040.00	20.00	832.00

# Estimate

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 23/2/21, 10.00 an

Estimate

SURVEYOR NAME: Steve (CLKK)

SURVEYOR SIGNATURE: 23/2/21, 10.00 am

DATE: 20-AM AL

Confirm &amp; accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party approval is required
- No illegal modifications
- Supplies are subject to availability

Authorized signatory and company stamp

REMARKS:

EXCIS - ?

P/P, R, PL, SY

3 days

Nett

4820.40

4,820.40

337.43

Total Payable

5,157.83

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.