

AIR ESTIMATE*

VEHICLE NO SHA8238D

16/02/21

MAKE :

MODEL HYU- I40

CHIANG / BRO

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / ee			\$1,106.00
2	REAR BUMPER BRACKET SIDE / LH / ee			\$35.60
10	REAR BUMPER CLIPS / ncc		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER X GNN			\$228.00
1	REAR BUMPER REINFORCEMENT X GNN			\$394.80
1	REAR BUMPER REFLECTOR LH / ser			\$32.00
1	REAR TAIL LAMP LH / CPA			\$1,052.20
				\$2,870.60
				20.00%
				\$574.12
				\$2,296.48
1	REAR BUMPER ADVERTISEMENT / ncc			\$50.00
1	REVERSE SENSOR ?			\$135.70
				\$172.13
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$600.00
	Check lighting			\$50.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
				\$1,470.00
	TOTAL LABOUR			\$1,470.00
	ESTIMATE TOTAL			\$3,938.61
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2 Days.

L/S

After repair photos

bmo Qiaf

22/2/21

3:30 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: