

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21002486/UTF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29146062

Claimant
Vehicle No : YP7833L

Insured Vehicle No : GBG3179M

Date of Loss: 23/02/2021

Nature of Claim: TP Claim No: 634033

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP7833L**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)

Engine No: 4P10C72306

Reg. Date: 17/11/2017 (Man. Year: 2017)

Chassis No: FEB21EA21638

Colour: White

Odometer: 172382 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15 (D)

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6/6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,104.50	2,526.00	8,578.50	77.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,350.00	2,460.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,914.50	3,876.00	11,038.50	74.01
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	14,914.50	3,100.00	11,814.50	79.21
+ GST 7.00/7.00% (S\$)	1,044.02	217.00	827.02	79.21
Nett Amount (S\$)	15,958.52	3,317.00	12,641.52	79.21

INSPECTION

Date of Assignment: 25/02/2021

Date Inspected: 23/02/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Mar 2021)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7833L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented/Bent	3,600.00 F	*1,800.00 FL
2	1		*SET TAILGATE FUSO STICKER	Necessary	185.00 F	*115.00 FL
3	1		*TAILGATE LOWER MEMBER	Repair	688.00 F	*- FL
4	1		*TAILGATE LOCK LATCH N/S	Repair	265.00 F	*- FL
5	1		*TAILGATE LOWER L BRACKET N/S	Repair	155.00 F	*- FL
6	1		*TAILGATE LOWER L BRACKET RUBBER N/S	Serviceable	82.50 F	*- FL
7	1		*TAILLAMP N/S	Cracked	380.00 F	*136.00 FL
8	1		*TAILLAMP BRACKET N/S	No such part	399.00 F	*- FL
9	1		*REAR LICENCE PLATE LAMP	Not Necessary	105.00 F	*- FL
10	1		*REAR LICENCE PLATE BRACKET	Bent	215.00 F	*165.00 FL
11	1		*TAILGATE INNER ALUMINIUM PLATE	Repair	1,500.00 FS	*- FS
12	1		*SET TAILGATE INNER ALUMINIUM PLATE RIVET	Necessary	60.00 FS	*40.00 FS
13	1		*SET TAILGATE 60KM/H STICKER	Necessary	20.00 FS	*10.00 FS
14	1		*TAILGATE WOODEN	Repair	1,080.00 FS	*- FS
15	1		*REAR LICENCE PLATE	Bent	20.00 FS	*14.00 FS
16	1		*REAR STEP PANEL CENTRE	Bent	900.00 FS	*600.00 FS
17	1		*REAR STEP PANEL CENTRE ALUMINIUM PLATE	Bent	250.00 FS	*200.00 FS
18	1		*REAR SAFETY BAR	Repair	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,104.50	3,080.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	554.00
Total Parts (\$\$)	11,104.50	2,526.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO SPRAY RUST PROOFING	New	80.00	30.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS }	New	1,500.00	800.00
5	TO LIFT UP CARGO DECK FOR REPAIR CHASSIS }	New	600.00	0.00
6	TO PUTTY & SPRAY PAINTING	New	1,500.00	500.00
Gross Labour Cost (\$)			3,810.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >