

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21002488/QQF3E2

**Date:** 30/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900083193  
Claimant Vehicle No : SGK16P Insured Vehicle No : SMK2875S  
Date of Loss: 19/02/2021 Nature of Claim: TP Claim No: 3562621694SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK16P**  
Make & Model: TOYOTA SIENNA, 1.5 G CVT ABS D/AIRBAG 2WD 5DR Engine No: 2NR8605680  
Reg. Date: 16/11/2016 (Man. Year: 2016) Chassis No: NSP1707028576  
Colour: Yellow Odometer: 148458 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 22/02/2021  
Date Inspected: 23/02/2021 Inspected At: Block 7 Sin Ming Industrial Estate Sector C #01-94  
Repairer : Mje Motor (HQ)  
Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Crumpled	0.00 F	*- F	
2	1		*REAR BUMPER SIDE BLACK RH	Scratched	0.00 F	*- F	
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
4	1		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*- F	
5	1		*REAR BUMPER SIDE RETAINER RH	Broken	0.00 F	*- F	
6	1		*TAILGATE	Repair	0.00 F	*- F	
					<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**