

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002491/KPA3Q2
Date: 01/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800060179
Claimant Vehicle No :	SGC8889B	Insured Vehicle No :	SCR138G
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	7260443422SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC8889B	Engine No:	2ZR0B90804
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800329878
Reg. Date:	18/10/2018 (Man. Year: 2018)	Odometer:	268240 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R16	Rear Tyre Size:	195/65 R16
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,047.50	0.00	3,047.50	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	600.00	1,730.00	74.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,377.50	600.00	4,777.50	88.84
+ GST 7.00/7.00% (S\$)	376.43	42.00	334.43	88.84

Nett Amount (S\$)	5,753.93	642.00	5,111.93	88.84
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,034.65		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 13/07/2021

Estimated Period of Repair: 2.0 days

Inspected At: MBM Wheelpower Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-15, Sin Ming AutoCare
Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	600.00 FL	*- FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	160.00 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Serviceable	160.00 FL	*- FL
4	10		*REAR BUMPER CLIP	Not Necessary	60.00 FL	*- FL
5	4		*REAR BUMPER SENSOR	Serviceable	1,000.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR RH	Serviceable	60.00 FL	*- FL
7	1		*REAR BUMPER COVER LH	Serviceable	190.00 FL	*- FL
8	1		*REAR BUMPER UPPER COVER	Serviceable	200.00 FL	*- FL
9	1		*REAR MUDGUARD	Repair	1,500.00 FL	*- FL
10	1		*NUMBER PLATE & HOLDER	Serviceable	50.00 FS	*- FS
11	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,030.00	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)	982.50	0.00
Total Parts (S\$)	3,047.50	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS ,INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	100.00
2	TO REMOVE & REFIT ALL SENSOR	New	50.00	0.00
3	TO APPLY ANTI RUST COATING	New	80.00	0.00
4	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,330.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >