

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002494/DBA3Q2
Date: 04/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993650
Claimant Vehicle No :	SKC6911K	Insured Vehicle No :	GBJ712C
Date of Loss:	18/02/2021	Nature of Claim:	TP
		Claim No:	6549496955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC6911K	Engine No:	CAX843932
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Chassis No:	WVWZZZ16ZCM009796
Reg. Date:	22/09/2011 (Man. Year: 2011)	Odometer:	160231 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,806.80	3,315.44	15,491.36	82.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,570.00	1,810.00	5,760.00	76.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,376.80	5,125.44	21,251.36	80.57
Approved Total (Overridden) (S\$)		4,100.00		

(S\$)	26,376.80	4,100.00	22,276.80	84.46
+ GST 7.00/7.00% (S\$)	1,846.38	287.00	1,559.38	84.46
Nett Amount (S\$)	28,223.18	4,387.00	23,836.18	84.46
+ Car Rental (11.0 x S\$120.00/day) (S\$)		1,320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,714.45		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 24/02/2021

Estimated Period of Repair: 6.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Buckled	2,830.00 FL	*1,371.00 FL
2	1		*REAR DOOR WINDOW MOULDING RH	Serviceable	340.00 FL	*- FL
3	1		*REAR DOOR BLACK PLASTIC RH	Necessary	199.00 FL	*38.00 FL
4	1		*REAR DOOR HANDLE RH	Repair	194.00 FL	*- FL
5	1		*REAR DOOR LOCK RH	Not Necessary	452.00 FL	*- FL
6	1		*REAR DOOR WEATHERSTRIP INNER RH	Not Necessary	499.00 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP OUTER RH	Deformed	495.00 FL	*168.50 FL
8	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	1,701.00 FL	*- FL
9	1		*REAR DOOR WINDOW MOTOR RH	Not Necessary	1,182.00 FL	*- FL
10	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	679.00 FL	*- FL
11	1		*ROCKER PANEL RH	Not Necessary	1,192.00 FL	*- FL
12	1		*REAR FENDER RH	Buckled	2,002.00 FL	*1,759.30 FL
13	1		*REAR FENDER INNER RH	Not Necessary	2,070.00 FL	*- FL
14	1		*REAR FENDER INNER SHIELD RH	Not Necessary	215.00 FL	*- FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	410.00 FL	*145.00 FL
16	1		*REAR RIM RH	Cut	1,712.00 FS	*450.00 FS
17	1		*REAR WHEEL BEARING RH	Not Necessary	412.00 FL	*- FL
18	1		*REAR WHEEL BEARING HUB RH	Not Necessary	492.00 FL	*- FL
19	1		*REAR KNUCKLE ARM RH	Not Necessary	902.00 FL	*- FL
20	1		*REAR LOWER ARM RH	Not Necessary	599.00 FL	*- FL
21	1		*REAR THRUST ARM RH	Not Necessary	601.00 FL	*- FL
22	1		*REAR ABSORBER RH	Not Necessary	705.00 FL	*- FL
23	1		*REAR UPPER ARM RH	Not Necessary	528.00 FL	*- FL
24	1		*REAR AXLE	Not Necessary	2,107.00 FL	*- FL
25	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*ROCKER PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
29	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
30	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*20.00 FS
31	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,968.00	4,011.80
- List Item Discount on L Items 20.00/20.00% (\$)	4,161.20	696.36

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					18,806.80	3,315.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	600.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
7	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	60.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	120.00
9	TO RNR FUEL TANK FILLER PIPER TO FACILITATE REPAIRS	New	100.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			7,570.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >